

HI-TACAN RWY 11L


TACAN CZQ Chan 76	APCH CRS 131°	Rwy Idg 11L 9279 11R 8008 TDZE 11L 336 11R 333 Arpt Elev 336
-----------------------------	-------------------------	--

AL-162 [USAF] FRESNO YOSEMITE INTL (KFAT)

DME required.

MISSED APPROACH: Climbing left turn to 2000 on CZQ TACAN R-124 to SELMA / 18.6 DME and hold.

ATIS 121.35 273.6	APP CON 119.6 351.95	TOWER 118.2 251.1	GND CON 121.7 348.6	CLNC DEL 124.35 348.6
-----------------------------	--------------------------------	-----------------------------	-------------------------------	---------------------------------



BEREN CZQ R-307 12.6		VGSI and descent angles not coincident (VGSI Angle 3.00/TCH 50)		2000 CZQ R-124		SELMA CZQ 18.6		ELEV 336		D		TDZE 11L 336 TDZE 11R 333		
10,000 8000		OXVEV 7		TACAN		FOVOR 4		131° 7.3 NM from FAF		Rwy 11L Idg 9279' Rwy 29R Idg 9227'				
127°		4800		2700		131°		362		371				
3.00° TCH 55		1420		6		7.3		363		391				
4 NM		3.3 NM						TWR 445		363				
CATEGORY	C		D		E									
S-11L	800-1½		464		(500-1½)									
SIDESTEP 11R	800-1½ 467 (500-1½)		800-2		467 (500-2)									
CIRCLING	920-1½		920-2		1140-2¾									
	584 (600-1½)		584 (600-2)		804 (900-2¾)									
REIL Rwy 11L and 11R HIRL Rwy 11L-29R MIRL Rwy 11R-29L TDZL/CL Rwy 29R														

HI-TACAN RWY 11L