

ILS RWY 22L (CAT II & III)
NEWARK LIBERTY INTL (EWR)

MISSED APPROACH: Climb to 500 then climbing right turn to 3000 on heading 225° and ARD VOR/DME R-069 to KILMA INT/ARD 27 DME and hold.



KILMA
JFK 30.2
115.9 JFK
R-265
Chan 106
085°
265°
113.8 RBV
R-024
Chan 85
ALTERNATE
MISSED
APCH FIX

**MISSED
APCH
FIX**
KILMA
ARD 27
112.9 SBJ
R-120
Chan 76
108.2 ARD
R-069
Chan 19
113.8 RBV
R-024
Chan 85

LOCALIZER 108.7
I-LSQ
Chan 24

KENNEDY
115.9 JFK
Chan 106

MSA SBJ 28 NM
3100

ELEV 18 TDZE 10

[illegible]

CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED