

25331

ILS or LOC RWY 36L
ORLANDO INTL (MCO)

MISSED APPROACH: Climb to 500 then climbing left turn to 3000 on heading 340° and ORL VORTAC R-248 to DNMR/ORL 6 DME and hold, continue climb-in-hold 3000.

Simultaneous approach authorized.

CATEGORY	A	B	C	D
S-ILS 36L		293/40	200 (200-¾)	
S-LOC 36L		440/55	347 (400-1)	
CIRCLING	740-1	644 (700-1)	740-1¼ 644 (700-1¼)	740-2 644 (700-2)

ORLANDO INTL (MCO)
ILS or LOC RWY 36L

SE-3, 06 AUG 2026 to 03 SEP 2026