


VORTAC LAL 116.0 Chan 107	APP CRS 096°	Rwy Ldg 8500 TDZE 132 Apt Elev 142
---	------------------------	---

VOR RWY 10
LAKELAND LINDER INTL (LAL)

RADAR required for procedure entry. DME or RADAR required.		ALSf-2 	MISSED APPROACH: Climb to 1000 then climbing left turn to 2000 on heading 294° and on LAL VORTAC R-330 to PLUMY INT/ PIE 33.4 DME and hold.
	Circling NA to Rwys 8 and 26. Circling Rwy 28 NA at night. For inop ALS, increase S-10 Cat C/D visibility to 1½ SM; increase UDATE fix minimums S-10 Cat C/D visibility to RVR 6000.		

ATIS 118.025	TAMPA APP CON 120.65 290.3	LAKELAND TOWER 124.5 236.775	GND CON 121.4
------------------------	--------------------------------------	--	-------------------------



				ELEV 142		D		TDZE 132	
CATEGORY	A		B		C		D		
S-10	700/24		568 (600-½)		700-1¼		568 (600-1¼)		
CIRCLING	700-1		558 (600-1)		720-1½ 578 (600-1½)		840-2¼ 698 (700-2¼)		
UPDATE FIX MINIMUMS									
S-10	540/24		408 (400-½)		540/40		408 (400-¾)		
CIRCLING	600-1 458 (500-1)		660-1 518 (600-1)		720-1½ 578 (600-½)		840-2¼ 698 (700-2¼)		
TDZL/RCLS Rwy 10 HIRL Rwys 5-23 and 10-28									
FAF to MAP 3.8 NM									
Knots 60 90 120 150 180									
Min:Sec 3:48 2:32 1:54 1:31 1:16									

SE-3, 06 AUG 2026 to 03 SEP 2026

SE-3, 06 AUG 2026 to 03 SEP 2026