

WAAS CH 72716 W02A	APP CRS 023°	Rwy Ldg 6607 TDZE 161 Apt Elev 168
--	------------------------	---

RNAV (GPS) Z RWY 2
RICHMOND INTL (RIC)

RNP APCH.

MALSR

MISSED APPROACH: Climb to 2000 direct IMASE and hold.

T For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -11°C (13°F) or above 54°C (130°F).
Rwy 2 helicopter visibility reduction below $\frac{3}{4}$ SM NA.

A5

ATIS		POTOMAC APP CON		RICHMOND TOWER		GND CON	
119.15	263.025	126.4	282.375 (001°-185°)	121.1	257.8	121.9	348.6
		126.75	307.2 (186°-360°)				

Procedure NA for arrival
on FAK VORTAC airway
radials 100 CW 220.

FLAT ROCK
FAK

2600
145°
(21.3)

MISSED APCH FIX

IMASE

Procedure NA for arrivals
at MATOX on V157
southwest bound.

Procedure NA for arrival
on HPW VORTAC airway
radials 178 CW 323.

HOPEW
HPWA

ELEV	168	D	TDZE	161
------	-----	----------	------	-----

RICHMOND, VIRGINIA

Amdt 1C 19JUL18

37°30'N-77°19'W

RICHMOND INTL (RIC)

RNAV (GPS) Z RWY 2

NE-3, 03 SEP 2026 to 01 OCT 2026

NE-3, 03 SEP 2026 to 01 OCT 2026