

FLYING CROWN (AK12) PVT 6 S UTC-9(-8DT) N61°06.40' W149°51.86'

ANCHORAGE

150 NOTAM FILE Not insp.

RWY 13-31: 1078X50 (TURF)

RWY 13: Thld dsplcd 30'. Trees.

RWY 31: Thld dsplcd 798'. Trees. Rgt tfc.

AIRPORT REMARKS: Unattended. Rwy conditions unmonitored, visual inspection recommended prior to use. Watch for pedestrians. Multiple sprinkler and equipment on or near rwy. And hill near end of rwys not maintained in winter. Railroad runs parallel to rwy, frequent train traffic. Operations not recommended during train traffic.

AIRPORT MANAGER: 907-245-1932

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE ANC.

ANCHORAGE (H) VOR/DME 113.15 TED Chan 78(Y) N61°10.07' W149°57.61' 125° 4.6 NM to fld. 93/18E.

VOR unusable:

041°-091° byd 25 NM blo 15,000'

091°-096° byd 20 NM blo 15,000'

096°-121° byd 25 NM blo 12,500'

121°-146° byd 25 NM blo 9,000'

DME unusable:

041°-091° byd 25 NM blo 15,000'

091°-096° byd 20 NM blo 15,000'

096°-121° byd 25 NM blo 12,500'


121°-146° byd 25 NM blo 9,000'

196°-206° byd 25 NM blo 3,500'

206°-211° byd 25 NM blo 4,000'

211°-221° byd 25 NM blo 3,500'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



LAKE HOOD (LHD)(PALH) P (ANG) 3 SW UTC-9(-8DT) N61°11.20' W149°57.92'

ANCHORAGE

AD

79 TPA-679(600) NOTAM FILE LHD

RWY 14-32: 2200X75 (GRVL-DIRT) MIRL

RWY 14: Tree.

RWY 32: Tree. Rgt tfc.

SERVICE: S4 FUEL 100, 100LL, JET A LGT SS-SR.

AIRPORT MANAGER: 907-266-2741


WEATHER DATA SOURCES: ASOS (907) 245-5432 (WX CAM)

COMMUNICATIONS: CTAF 126.8 ATIS 125.6 (907-245-5432)

Ⓡ **ANCHORAGE APP/DEP CON** 119.1 363.2

TOWER 126.8 (907-245-5432)

CLNC DEL 119.4



CONTINUED ON NEXT PAGE

