UPPER LAKE

GRAVELLY VALLEY (1Q5) 17 N UTC-8(-7DT) N39°27.04′ W122°57.28′

SAN FRANCISCO

SAN FRANCISCO L-2F, 3A

IAP

1900 TPA—2700(800) NOTAM FILE OAK

RWY 01–19: 4050X200 (GRVL) S–12.5

RWY 01: Trees.

RWY 19: Hill.

AIRPORT REMARKS: Unattended. Be alert for occasional wildlife on rwy. Hang glider opr particularly summer months. Do not land south of Hull Mountain Road. No Idg on Rwy 19 due to hill northeast of arpt. No tkf on Rwy 01 due to hill northeast of arpt. Tall trees on both sides of rwy. Trees penetrate the transitional surface on both sides of the arpt. Rwy 01–19 not regularly maintained, rwy may be rough, uneven and rutted.

AIRPORT MANAGER: 707-275-1401 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

VACAVILLE

NUT TREE (VCB)(KVCB) 2 NE UTC-8(-7DT) N38°22.69′ W121°57.67′ 117 B NOTAM FILE VCB

RWY 02-20: H4700X75 (ASPH) S-30 MIRL

RWY 02: REIL. PAPI(P2L)—GA 3.75° TCH 27'. Tree.

RWY 20: REIL. PAPI(P2L)—GA 3.75° TCH 27'. Rgt tfc.

SERVICE: S4 FUEL 100LL, JET A LGT After 0600Z‡ ACTIVATE MIRL and parallel twy lgts Rwy 02–20; PAPI and REILs Rwy 02 and Rwy 20—CTAE.

AIRPORT REMARKS: Attended Mon-Fri 1400-0100Z‡. No turns to crosswind below 800° MSL, remain west of interstate highway for Rwy 20, noise sensitive area west of arpt. Rwy 02 calm wind rwy. Twy lgts on parallel twy only.

AIRPORT MANAGER: 707-469-4600

WEATHER DATA SOURCES: ASOS 134.75 (707) 448-1594.

COMMUNICATIONS: CTAF 122.85

®TRAVIS APP/DEP CON 128.4

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

RADIO AIDS TO NAVIGATION: NOTAM FILE SAC

SACRAMENTO (H) VORTACW 115.2 SAC Chan 99 N38°26.62′ W121°33.10′ 242° 19.7 NM to fld. 3/17E.

