

**MUSKEGON CO** (MKG)(KMKG) 4 S UTC-5(-4DT) N43°10.06' W86°14.13'

629 B ARFF Index—See Remarks NOTAM FILE MKG

**RWY 06-24:** H6501X150 (ASPH-PFC) S-120, D-250, 2S-175, 2D-497 PCN 62 F/A/X/T HIRL**RWY 06:** REIL. VASI(V4L)—GA 3.0° TCH 45'. Trees.**RWY 24:** MALSR. VASI(V4L)—GA 3.0° TCH 58'. Tree.**RWY 14-32:** H6100X150 (ASPH-PFC) S-120, D-230, 2S-165, 2D-430 PCN 56 F/A/X/T HIRL**RWY 14:** REIL. PAPI(P4L)—GA 3.0° TCH 45'. RVR-R**RWY 32:** MALSR. RVR-T**RUNWAY DECLARED DISTANCE INFORMATION****RWY 06:** TORA-6501 TODA-6501 ASDA-6501 LDA-6501**RWY 14:** TORA-6100 TODA-6100 ASDA-6100 LDA-6100**RWY 24:** TORA-6501 TODA-6501 ASDA-6501 LDA-6501**RWY 32:** TORA-6100 TODA-6100 ASDA-6100 LDA-6100**SERVICE:** S4 **FUEL** 100LL, JET A **OX2** **LGT** When ATCT clsd actvt  
MALSR Rwy 24; REIL Rwy 06; HIRL Rwy 06-24—CTAF. VASI Rwy 06 & 24 opr constly.**AIRPORT REMARKS:** Attended Nov-Mar, Mon-Fri 1100-0300Z‡,  
Sat-Sun 1100-0200Z‡, Apr-Oct, Mon-Fri 1000-0200Z‡,  
Sat-Sun 1000-0100Z‡. Otr hrs call 231-798-2126. Deer and  
birds on and invof of arpt. Rwy 14-32 CLOSED dly 0400-1100Z‡.  
Class 1, ARFF Index A. ARFF Index B avbl upon req, call amgr. 24  
hr PPR for unsked acr ops with gtr than 30 pax seats, call amgr. Ldg fee.**AIRPORT MANAGER:** 231-798-4596**WEATHER DATA SOURCES:** ASOS (231) 798-1317**COMMUNICATIONS:** CTAF 126.25 ATIS 124.3 UNICOM 122.95**RCO** 122.5 (LANSING RADIO)Ⓡ **GREAT LAKES APP/DEP CON** 119.8 (North) 133.825 (South) (1030-0500Z‡)Ⓡ **CHICAGO CENTER APP/DEP CON** 132.275 (0500-1030Z‡)**TOWER** 126.25 (1100-0400Z‡) **GND CON** 121.6**CLEARANCE DELIVERY PHONE:** For CD when ATCT clsd ctc Great Lakes Apch at 269-459-3344, when Apch clsd ctc Chicago  
ARTCC at 630-906-8921.**AIRSPACE:** CLASS D svc 1100-0400Z‡; other times CLASS E.**TRSA** svc ctc **APP CON****RADIO AIDS TO NAVIGATION:** NOTAM FILE MKG.(L) **TACAN** Chan 99 MKG (115.2) N43°10.16' W86°02.36' 270° 8.6 NM to fld. 659/1W.


TACAN AZIMUTH unusable:

055°-090° byd 10 NM blo 4,000'

281°-360° byd 10 NM blo 8,000'

DME unusable:

281°-360° byd 10 NM blo 8,000'

**ILS/DME** 109.5 I-CJH Chan 32 Rwy 24. Class IA. ILS/DME unmonitored when ATCT clsd. Autopilot coupled  
apchs na below 1,150'. DME unusable byd 28° right of course.**ILS/DME** 109.9 I-MKG Chan 36 Rwy 32. Class IE. LOC and glideslope unmntd when ATCT clsd.**ASR** (1100-0400Z‡)**CHICAGO****H-5E, 10F, L-281****IAP, AD****NAPOLEON****NAPOLEON** (3NP) 1 NW UTC-5(-4DT) N42°10.26' W84°15.56'

963 NOTAM FILE LAN

**RWY 09-27:** 2740X200 (TURF)**RWY 09:** Trees.**RWY 27:** Tree.**RWY 15-33:** 2500X160 (TURF)**RWY 15:** Thld dspld 690'. Road.**RWY 33:** Thld dspld 550'. Bldg.**AIRPORT REMARKS:** Attended irregularly. Oil tanks south of arpt. Ultralight ops in grass west of Rwy 15-33. Deer and large birds  
on and invof rwy. Rwy not plowed in winter. Rwy soft in spring. Rwy 09 dspld thr 1537'. Rwy 09-27 and Rwy 15-33  
marked with 3' yellow cones; dspld thlds marked with three 3' yellow cones each side of rwy.**AIRPORT MANAGER:** 517-740-0333**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at  
440-774-0224/0490.**DETROIT**