

FRUITPORT

FLYING-A-RANCH (39Z) 2 SE UTC-5(-4DT) N43°06.31' W86°07.28'
630 TPA—1430(800) NOTAM FILE LAN

CHICAGO

RWY 09-27: 1925X70 (TURF) LIRL

RWY 09: Thld dsplcd 327'. Trees.

RWY 27: Trees. Rgt tfc.

SERVICE: S4 LGT Airport lighting not for public use.

AIRPORT REMARKS: Attended irregularly. Arpt is CLOSED Nov-Mar. No snow removal. Fuel avbl for emerg use only. Rwy 09-27 rwy rough and uneven. Rwy 09-27 and dsplcd thld marked with 3' yellow cones.

AIRPORT MANAGER: 616-846-3977

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3344, when Apch clsd ctc Chicago ARTCC at 630-906-8921.

GAVAGAN FLD (See YALE on page 251)

GAYLORD

GAYLORD RGNL (GLR)(KGLR) 1 SW UTC-5(-4DT) N45°00.78' W84°42.21'
1328 B NOTAM FILE GLR

LAKE HURON

H-2L, L-31C

IAP

RWY 09-27: H6579X150 (ASPH) D-100, 2S-127 HIRL

RWY 09: MALSR. PAPI(P4L)—GA 3.0° TCH 38'. Trees.

RWY 27: REIL. PAPI(P4L)—GA 3.0° TCH 45'. Pole.

RWY 18-36: H4200X75 (ASPH) S-12.5 MIRL

RWY 18: REIL. PAPI(P4L)—GA 3.0° TCH 40'.

RWY 36: REIL. PAPI(P4L)—GA 3.0° TCH 40'.

SERVICE: S4 FUEL 100LL, JET A+ OX 3, 4 LGT Actvt MALSR Rwy 09; REIL Rwy 27, 18, & 36; PAPI Rwy 09, 27, 18, & 36; HIRL Rwy 09-27; MIRL Rwy 18-36—CTAF. Rwy 36 PAPI unusbl byd 8 degs left & 7 degs right of cntrln.

AIRPORT REMARKS: Attended May-Oct 1230-2300Z, Nov-Apr 1130-2200Z. For attendant aft hrs call amgr. Unatndd Thanksgiving, Christmas, & New Years Day. Deer and birds on and invof arpt. Admin bldg aces 5-3-2-1. Fuel subj aft hrs call-in fee. Ldg fee for turbine, jet, & twin-eng acct waived with mnm fuel purchase. Ovngt prkg fee. Mil trg act invof arpt assoc with R-4201A/B.

AIRPORT MANAGER: 989-732-4218

WEATHER DATA SOURCES: ASOS 118.375 (989) 732-1571.

COMMUNICATIONS: CTAF/UNICOM 122.8

RCO 122.55 (LANSING RADIO)

® MINNEAPOLIS CENTER APP/DEP CON 134.6

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE GLR.

(L) (L) VORW/DME 109.2 GLR Chan 29 N45°00.75' W84°42.26' at fld. 1318/6W.

VOR portion unusable:

182°-195° btn 19 and 21 NM

DME unusable:

Byd 30 NM blo 3,500'

BANGU NDB (LOMW) 375 GL N45°00.88' W84°48.48' 097° 4.4 NM to fld. 1385/6W.

ILS 111.1 I-GLR Rwy 09. Class IE. LOM BANGU NDB. Unmonitored.

