

KANKAKEE

GREATER KANKAKEE (IKK)(KIKK) 3 S UTC-6(-5DT) N41°04.28' W87°50.78'

CHICAGO
H-5E, L-27C
IAP

630 B NOTAM FILE IKK

RWY 04-22: H5981X100 (ASPH-PFC) S-60, D-95 HIRL

RWY 04: MALSR. PAPI(P4L)—GA 3.0° TCH 51'.

RWY 22: REIL. PAPI(P4L)—GA 3.0° TCH 37'.

RWY 16-34: H4398X75 (ASPH) S-30, D-40 MIRL

RWY 16: PAPI(P4L)—GA 3.0° TCH 40'. Tree.

RWY 34: PAPI(P4L)—GA 3.0° TCH 37'.

SERVICE: FUEL 100LL, JET A LGT Actvt MALSR Rwy 04; REIL Rwy 22; HIRL Rwy 04-22; MIRL Rwy 16-34—CTAF. HIRL Rwy 04-22 preset to low intst; to incr intst—CTAF.

AIRPORT REMARKS: Attended Apr-Oct 1300-0100Z†, Nov-Apr 1330-2300Z†. PPR req for ultralight ops ctc amgr. Ultralight act in grass area W of Rwy 04-22 & E of Rwy 16-34. Deer and waterfowl on and infov.

AIRPORT MANAGER: 815-939-1422

WEATHER DATA SOURCES: AWOS-3 128.475 (815) 939-4044.

COMMUNICATIONS: CTAF/UNICOM 123.0

RCO 122.2 (KANKAKEE RADIO)

Ⓡ CHICAGO CENTER APP/DEP CON 132.5


CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Chicago ARTCC at 630-906-8921.

RADIO AIDS TO NAVIGATION: NOTAM FILE IKK.

PEOTONE (L) (L) VORTACW 113.2 EON Chan 79 N41°16.18' W87°47.46' 190° 12.1 NM to fld. 689/2E.

LUKOW NDB (LOMW) 272 IK N41°01.07' W87°54.23' 039° 4.1 NM to fld. 669/0E.

ILS 108.7 I-IKK Rwy 04. Class IT. LOM LUKOW NDB.



KANKAKEE (3KK) 3 SW UTC-6(-5DT) N41°06.00' W87°55.00'

CHICAGO

625 TPA—1425(800) NOTAM FILE IKK

RWY 09-27: 2644X300 (TURF) LIRL(NSTD)

RWY 27: Thld dspld 285'. Road.

RWY 18-36: 2564X200 (TURF)

RWY 36: Thld dspld 900'. Trees.

SERVICE: S4 LGT Rwy 09-27 NSTD LIRL; variable ints and spacing and non-frangible mountings.

AIRPORT REMARKS: Attended Mon-Fri 1300-0100Z†, Sat-Sun irregularly. Contact manager in advance for rwy lgts. Ultralight activity on and inof arpt. Rwy 27 and Rwy 36 dspld thld marked with white rocks. 400 ft ovrn end of Rwy 27.

AIRPORT MANAGER: 815-932-4222

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

KEWANEE MUNI (EZI)(KEZI) 3 SW UTC-6(-5DT) N41°12.31' W89°57.83'

CHICAGO
L-27C
IAP

858 B TPA—See Remarks NOTAM FILE IKK

RWY 09-27: H4500X75 (ASPH) S-20 MIRL

RWY 09: PVASI(PSIL)—GA 3.5° TCH 27'.

RWY 27: PVASI(PSIL)—GA 3.0° TCH 23'.

RWY 01-19: H3200X60 (ASPH) S-20 MIRL 0.5% up S

SERVICE: S4 FUEL 100LL LGT MIRL Rwy 09-27 preset on low ints; to increase ints and ACTIVATE MIRL Rwy 01-19 and twy lgts—CTAF.

Rwy 09 PVASI unusable byd 6° left and right of centerline. Rwy 27 PVASI unusable byd 6° left and right of centerline.

AIRPORT REMARKS: Attended Mon-Fri 1400-0000Z†, Sat-Sun 1500-2300Z†. Ultralight act on and infov arpt. Hospital heliport 1.2 NM northeast of arpt. TPA—1258 (400) ultralight acft. Automated wx adzy avbl on CTAF - 4 mic clicks to actvt.

AIRPORT MANAGER: 309-853-8671

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ QUAD CITY APP/DEP CON 133.275 (1130-0430Z†)

Ⓡ CHICAGO CENTER APP/DEP CON 118.75 (0430-1130Z†)

CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

RADIO AIDS TO NAVIGATION: NOTAM FILE IKK.

BRADFORD (H) (H) VORTACW 114.7 BDF Chan 94 N41°09.58' W89°35.27' 279° 17.3 NM to fld. 810/0E.

VOR portion unusable.

189°-199° blo 3,500' btn 25 and 35 NM

