OKLAHOMA 189

EUFAULA

EUFAULA MUNI (FØ8) 2 W UTC-6(-5DT) N35°17.90´ W95°37.64´

635 B NOTAM FILE MLC

RWY 17-35: H3000X60 (ASPH) S-4 MIRL 0.4% up N RWY 17: PAPI(P2L)—GA 3.5° TCH 46'. Trees.

RWY 35: PAPI(P2L)-GA 3.5° TCH 45'.

SERVICE: LGT MIRL Rwy 17-35 preset low ints, to incr ints,

ACTIVATE-CTAF.

AIRPORT REMARKS: Unattended. Ultralgts on and invof arpt.

AIRPORT MANAGER: 918-689-2534


COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at

817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE MLC.

MC ALESTER (L) TACAN Chan 57 MLC (112.0) N34°50.97′ W95°46.94′ 008° 28.0 NM to fld. 782/8E.



FOUNTAINHEAD LODGE AIRPARK (ØF7) 6 N UTC-6(-5DT) N35°23,32′ W95°36,02′

670 B NOTAM FILE MLC

RWY 18-36: H3000X50 (ASPH) S-8 MIRL

RWY 36: Tree.

SERVICE: LGT ACTIVATE MIRL Rwy 18-36—CTAF. MIRL OTS indef.


AIRPORT REMARKS: Unattended. Deer on and invof rwy. Rwy 18-36 moderate to severe cracking and raveling.

AIRPORT MANAGER: 918-689-5311

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at

817-858-7584.



FAIRMONT FLD (10K) 2 NE UTC-6(-5DT) N36°21.91′ W97°40.07′

WICHITA

1170 NOTAM FILE Not insp.

RWY 17-35: 2540X65 (TURF) 0.3% up S

AIRPORT REMARKS: Unattended. Wildlife on and invof arpt. 4 ft seasonal crops at both apch ends Rwy 17-35. Ldg fee.

AIRPORT MANAGER: 580-242-6627

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Vance Apch at 580-213-6765. when Vance Apch is clsd, ctc Kansas City ARTCC at 913-254-8508.

SC, 19 MAY 2022 to 14 JUL 2022

DALLAS-FT WORTH L-15E

DALLAS-FT WORTH