

**EDGEWOOD**

**SANDIA AIRPARK ESTATES EAST** (1N1) 2 NE UTC-7(-6DT) N35°05.68' W106°09.87' **ALBUQUERQUE**  
 6565 B NOTAM FILE ABQ **L-81**  
**RWY 09-27:** H4830X30 (ASPH) LIRL(NSTD) 1.0% up W  
**RWY 09:** Bldg.  
**SERVICE:** S4 **FUEL** 100LL **LGT** ACTVT NSTD LIRL Rwy 09-27—CTAF (5 clicks). NSTD LIRL Rwy 09-27 irregular spacing, color, single fixture on Rwy 09 thld, no thld lgts Rwy 27, several fixtures missing or inoperative. Auxiliary wind sock near Rwy 09 thld illuminated with solar power. Rotating bcn OTS indef.  
**AIRPORT REMARKS:** Attended Tue-Sat 1600-2100Z. Self svc fuel with credit card. Emergency phone 505-281-5717 (Police) or 505-281-4697 (Fire Department). For power plant repairs call 505-281-3364. Wildlife on or in vicinity of arpt. Rwy 09 and Rwy 27 centerline faded and portions missing.  
**AIRPORT MANAGER:** 505-263-3759  
**COMMUNICATIONS:** CTAF/AUNICOM 122.8  
**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE SAF.  
**SANTA FE (L) (L) VORTACW** 110.6 SAF Chan 43 N35°32.43' W106°03.90' 177° 27.2 NM to fld. 6268/13E.  
 VORTAC unusable:  
 015°-030° byd 30 NM blo 14,600'  
**COMM/NAV/WEATHER REMARKS:** Automated UNICOM: 3 clicks wind adzy, 4 clicks for all other adzy info.

**ESPANOLA**

**OHKAY OWINGEH** (E14) 3 NE UTC-7(-6DT) N36°01.57' W106°02.72' **DENVER**  
 5790 B NOTAM FILE ABQ **H-4L, 6F, L-81**  
**RWY 16-34:** H5007X75 (ASPH) S-18 PCN 7 F/D/Y/T MIRL  
**RWY 16:** Thld dsplcd 324'.  
**RWY 34:** Brush.  
**SERVICE:** **FUEL** 100LL, JET A **LGT** ACTIVATE MIRL Rwy 16-34—CTAF.  
**AIRPORT REMARKS:** Unattended. 100LL and Jet A fuel avbl 24 hrs self svc with major credit card. Wildlife on or in vicinity of arpt. Main gate locked at all times. Arpt access gate combination-4751. No disp thld or markings on Rwy 16. Rwy 16-34, 2 to 4 inch wide cracks across rwy, aprx every 50-100', 1 to 1.5 inch in depth. Call Pueblo or arpt manager to enter/exit 505-747-0700 or 505-660-6113.  
**AIRPORT MANAGER:** (505) 901-7397  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE SAF.  
**SANTA FE (L) (L) VORTACW** 110.6 SAF Chan 43 N35°32.43' W106°03.90' 349° 29.1 NM to fld. 6268/13E.  
 VORTAC unusable:  
 015°-030° byd 30 NM blo 14,600'

**ESTANCIA MUNI** (E92) 1 E UTC-7(-6DT) N34°45.80' W106°02.48' **ALBUQUERQUE**  
 6100 NOTAM FILE ABQ  
**RWY 08-26:** 4000X50 (GRVL)  
**RWY 08:** Pole.  
**RWY 26:** Brush.  
**SERVICE:** **LGT** Rwy 08 markings NSTD, thld and edge marked with reflective material. Several reflectors missing and reflective material in poor cond. Rwy 26 markings NSTD, thld and edge marked with reflective material. Several reflectors missing and reflective material in poor cond.  
**AIRPORT REMARKS:** Unattended. Cattle and birds on and invof rwy. Rwy 08-26 soft when wet. Rwy 08 +12' tree 134' from thld, 78' rgt of cntrln. Rwy 26 +3-5' brush 0-200' from thld, 125' left and rgt of cntrln. Rwy 08-26 scattered brush in primary surface, +2-3 ft high, 30-40 ft fm cntrln both sides.  
**AIRPORT MANAGER:** 505-384-2708  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.