MAPLE GROVE HELIPORT (E66) 4 N UTC-5(-4DT) N42°43.03′ W84°03.72′ 897 B NOTAM FILE LAN

DETROIT COPTER

187

HELIPAD H1: 32X32 (TURF)

HELIPAD H2: H12X12 (CONC)

RWY LGTS(NSTD)

HELIPAD H2: NSTD.

HELIPAD H3: 20X20 (MATS)

RWY LGTS(NSTD)

HELIPAD H3: NSTD

HELIPAD H4: 50X50 (TURF)

SERVICE: S4 LGT Nstd abn due to instln - Icl use only. Actvt nstd abn—123.025. Actvt nstd perimeter Igts Helipad H2 & H3; nstd TRCV Helipad H2 & H3—123.025. H2 nstd perimeter lgts due to lctn & dspl - lcl use only. H2 VGSI: nstd TRCV due to instln - Icl use only. H3 nstd perimeter lgts due to lctn & dspl - Icl use only. H3 VGSI: nstd TRCV due to instln -Icl use only.

HELIPORT REMARKS: Attended 1400-2200Z‡. HIp colocated with 65G arpt, be alert for fixed wing acft & PJE act. Extsv acft trg, two-way rdo coms rqrd—CTAF. H1, H2, & H3 90 ft trees, 231 ft west. H1 mkg defined by mowing. H2 mkd with 3 ft Igtd yellow cones. H2 48 ft ant, 485 ft south. H3 max gwt 3000 lb. H4 pri helipad. H4 mkg defined by mowing.

AIRPORT MANAGER: 517-223-7809 COMMUNICATIONS: CTAF 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490.

## **FRANKENMUTH**

WM 'TINY' ZEHNDER FLD (66G) 2 SE UTC-5(-4DT) N43°18.86′ W83°42.60′

DETROIT

639 NOTAM FILE LAN

RWY 09-27: 2500X100 (TURF) 0.3 up E

RWY 09: Thid dsplcd 394'. Road.

AIRPORT REMARKS: Unattended. Deer and birds on and invof arpt. No snow removal, call 989-728-3684 to vfy conds. Rwy 09-27 soft in spring and aft hvy rain. Rwy 09, -7' ditch 60' fm thld. Rwy 27 +8' seasonal crops, 10' fm thr, 100' left and right of cntrln. Rwy 09-27 and dthr mkd with 3' yellow cones.

AIRPORT MANAGER: 989-728-3864

**COMMUNICATIONS: CTAF** 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490.

FRANKFORT DOW MEML FLD (FKS)(KFKS) 2 SE UTC-5(-4DT) 633 B NOTAM FILE FKS

N44°37.51′ W86°12.05′

**GRFFN BAY** L-31B

IAP

RWY 15-33: H4050X75 (ASPH) S-25 MIRL 0.7% up NW

RWY 15: Thid dsplcd 1094'. Road.

RWY33: REIL. PAPI(P2R)—GA 3.0° TCH 35'. Thid dsplcd 111'. Tree. SERVICE: FUEL 100LL LGT Actvt REIL Rwy 33; PAPI Rwy 33; MIRL Rwy 15-33-CTAF (3 mike clicks turns off).

AIRPORT REMARKS: Attended ireg. On call attendant 231-352-9118. Deer and birds on and invof arpt. UAS opr west of Rwy 15-33. Hang glider activity along Lake Michigan lakeshore. Fuel self ser via credit card. Ramp fee for commercial acft. Arpt bcn located on hill 1.25 miles northwest of arpt. Admin bldg aces, press 5-3-2-1.

AIRPORT MANAGER: 231-651-0751

WEATHER DATA SOURCES: AWOS-3P 118.325 (231) 352-7573. Wind unrel. COMMUNICATIONS: CTAF/UNICOM 123.05

®MINNEAPOLIS CENTER APP/DEP CON 132.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588

**3 3** G G €3 **(3** €3 €3 a **(3 (3** €3