

WHITEFIELD

MOUNT WASHINGTON RGNL (HIE)(KHIE) 3 E UTC-5(-4DT) N44°22.05' W71°32.75' MONTREAL
1072 B TPA-3072(2000) NOTAM FILE HIE L-32H
RWY 10-28: H4001X75 (ASPH) S-30 MIRL 0.6% up E IAP
RWY 10: REIL. PAPI(P4L)-GA 3.5° TCH 45'.
RWY 28: REIL. Rgt tfc.
SERVICE: S4 FUEL 100LL LGT ACTIVATE REIL Rwy 10 and Rwy 28; PAPI Rwy 10; MIRL Rwy 10-28-CTAF.
AIRPORT REMARKS: Attended irregularly. Wildlife on and invof arpt. Arpt conds not rglrly mnt. 100LL self svc avbl 24 hrs with
credit card. Cold temperature airport. Altitude correction required at or below -29C. Rwy 28 trans line across apch 20:1 +
and marked with day glow balls. Rising trrn lctd 3NM SE of arpt.
AIRPORT MANAGER: 603-837-9532
WEATHER DATA SOURCES: ASOS 118.525 (603) 837-2769.
COMMUNICATIONS: CTAF/UNICOM 122.8
WHITEFIELD RCO 122.4 (BANGOR RADIO)
® BOSTON CENTER APP/DEP CON 135.7
CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Boston ARTCC at 603-879-6859.
RADIO AIDS TO NAVIGATION: NOTAM FILE MPV.
MONTPELIER (VL) (DH) VORW/DME 116.9 MPV Chan 116 N44°05.13' W72°26.96' 082° 42.5 NM to fld.
2086/16W.
VOR unusable:
010°-020° byd 25 NM blo 7,500'
015°-031° byd 40 NM
032°-042° byd 40 NM blo 5,000'
032°-042° byd 65 NM
043°-060° byd 40 NM
045°-060° byd 24 NM blo 8,500'
170°-182° byd 40 NM
210°-275° byd 40 NM
DME unusable:
045°-060° byd 24 NM blo 8,500'
MAHN NDB (MHW) 386 GMA N44°21.74' W71°41.15' 104° 6.0 NM to fld. 1425/17W. NOTAM FILE HIE. NDB
unmonitored.
NDB unusable:
Byd 15 NM blo 9,000'