

FORT MORGAN MUNI (FMM)(KFMM) 5 N UTC-7(-6DT) N40°20.13' W103°48.25'

CHEYENNE
H-5A, L-10F
IAP

4595 B TPA-5626(1031) NOTAM FILE DEN

RWY 14-32: H5731X75 (ASPH) S-30 MIRL 1.5% up NW

RWY 14: REIL. PAPI(P2L)-GA 3.0° TCH 28'.

RWY 32: REIL. PAPI(P2L)-GA 3.0° TCH 27'.

RWY 17-35: 5216X80 (TURF-DIRT) 0.6% up N

RWY 35: Road.

RWY 08-26: 2468X100 (TURF)

RWY 26: Road.

SERVICE: FUEL 100LL, JET A1 LGT ACTIVATE REIL Rwy 14 and Rwy 32; MIRL Rwy 14-32-CTAF.

AIRPORT REMARKS: Attended Mon-Sat 1500-0000Z. Fuel avbl 24 hrs with credit card. Parachute Jumping. Be alert, intensive USAF student training invof Colorado Springs and Pueblo Colorado. Rwy 17-35, 21 road 100' east of and parallel to rwy cntrln full length. NOTE: See Special Notices-Aerobatic Operations in Colorado. USAF 306 FTG Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.

AIRPORT MANAGER: 970-867-8414

WEATHER DATA SOURCES: AWOS-3PT 132.95 (970) 867-1992.

COMMUNICATIONS: CTAF/UNICOM 123.05

② DENVER CENTER APP/DEP CON 118.475


CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE AKO.

AKRON (VH) (H) VORW/DME 114.4 AKO Chan 91 N40°09.33' W103°10.78' 278° 30.6 NM to fld. 4623/13E.

VOR unusable:

228°-232° byd 40 NM



FREMONT CO (See CANON CITY on page 319)

GILL N40°30.23' W104°33.18' NOTAM FILE DEN.

CHEYENNE
H-5A, L-10F

(VH) (DH) VORW/DME 114.2 GLL Chan 89 210° 5.4 NM to Greeley-Weld Co. 4904/13E.

VOR unusable:

193°-204° byd 40 NM blo 7,800'

193°-204° byd 50 NM

226°-240° byd 40 NM

254°-263° byd 40 NM blo 16,000'

RCO 122.5 (DENVER RADIO)

GLENWOOD SPRINGS MUNI (GWS)(KGWS) 3 S UTC-7(-6DT) N39°30.36' W107°18.55'

DENVER
L-9E

5916 NOTAM FILE DEN

RWY 14-32: H3305X50 (ASPH) S-15 0.3% up NW

RWY 14: Trees.

RWY 32: PAPI(P2L)-GA 4.0° TCH 30'. Road.

SERVICE: S4 FUEL 100LL, JET A1 QX 3, 4

NOISE: Noise abatement: When wind and weather permit use Rwy 32 for arrival and Rwy 14 for departure. No touch and go lds.

AIRPORT REMARKS: Attended Mon-Fri 1500-0000Z. Fuel avbl 24 hrs via self-serve credit card pump. Arpt Manager on call at 970-445-0965. FBO PH: 970-945-3073. Gusty winds frequently in vicinity of arpt. Wildlife on and invof arpt.

Numerous +25' buildings; trees; equipment; tie downs approximately 150' from centerline-both sides of rwy full length.

Rwy 32 has 20' hangars and +30' antenna 200' left of centerline at thld. Paragliding ops vicinity 1 to 2 miles northwest of arpt up to 18,000' MSL. Automated super unicorn. Click 3 times for arpt information.

AIRPORT MANAGER: 970-445-0965

COMMUNICATIONS: CTAF/AUNICOM 123.0

RCO 122.2 (DENVER RADIO)

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.

RED TABLE (VH) (DH) VORW/DME 113.0 DBL Chan 77 N39°26.36' W106°53.68' 270° 19.7 NM to fld.

11800/12E.

VOR unusable:

040°-056° byd 40 NM

057°-074° byd 40 NM blo 16,300'

057°-074° byd 65 NM

075°-100° byd 40 NM

115°-130° byd 40 NM

160°-200° byd 40 NM

COMM/NAV/WEATHER REMARKS: Automated UNICOM, 3 clicks adzy.