

HAINES JUNCTION YT (CYHT) 2 NW YUKON GOVT UTC-8(-7DT) N60°47.37' W137°32.71' **WHITEHORSE**
 2150 NOTAM FILE CYHT Not insp. **H-1C, L-1B**
RWY 05-23: 5002X100 (GRVL) LIRL
RWY 05: REIL. PAPI(P2L) Rgt tfc.
RWY 23: REIL. PAPI(P2L)
AIRPORT REMARKS : Attended Mon-Fri. Fuel storage by permit only ctc opr. Rwy 05-23 ltd win maint. Cable span on Paint Mountain 3 NM north. Ngt ops not recommended unless both hazard beacons opr. Hi terrain all quads. Gnd rises sharply north of apch to Rwy 23. Only pilots familiar with lcl terrain should use arpt dur hrs of darkness. Ngt ops—all ops south of rwy within 2 NM of rwy thlds.
COMMUNICATIONS:
RCO 123.375 (WHITEHORSE RADIO)
COMM/NAV/WEATHER REMARKS: Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA). Edmonton IFR: 888-358-7526. WxCam.

HOUSTON BC N54°27.14' W126°39.03' **H-1D**
VOR/DME 114.7 YYD Chan 94 304° 29.1 NM to Smithers./17E.

KITIMAT BC N54°03.25' W128°40.21' **L-1D**
NDB(HZ) 203 ZKI 348° 25.1 NM to Terrace./19E.

MASSET BC (CZMT) 1.5 SW UTC-8(-7DT) N54°01.63' W132°07.50' **KETCHIKAN**
 19 B AOE NOTAM FILE CYZP Not insp. **H-1D, L-1C**
RWY 13-31: H4924X100 (ASPH) MIRL
RWY 13: SSALR. REIL. PAPI(P2L)—GA 3.0°.
RWY 31: ODALS. REIL. PAPI(P2L)—GA 3.5°. Thld dsplcd 250'. Rgt tfc.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 13: TORA-4924 TODA-4924 ASDA-4924 LDA-4924
RWY 31: TORA-4924 TODA-4924 ASDA-4924 LDA-4674
SERVICE: FUEL JET A1 **LGT** ACTIVATE MIRL Rwy 13-31, PAPI and REIL Rwys 13 and 31—122.7. REIL avbl hi instst only. Twy B unlgtd.
AIRPORT REMARKS : Attended 1600-0100Z‡ (DT 1500-0000Z) exc statutory hols May 1-Sep 30; 1600-2000Z‡ (DT 1500-1900Z) and 2100-0000Z‡ (DT 2000-2300Z) Sun-Fri exc statutory hols Oct 1-Apr 30. O/T call out chg. Amgr after hrs-250-626-7458. Rwy 31 rgt tfc. Fuel avbl 1600-0100Z‡ (DT 1500-0000Z) exc statutory hols May 1-Sep 30; 1600-2000Z‡ (DT 1500-1900Z) and 2100-0000Z‡ (DT 2000-2300Z) Sun-Fri exc statutory hols Oct 1-Apr 30. O/T 2 hrs PN cost recovery. 24 hr svc call out phone located at the centre of the airside outside of the terminal building. Rwy 13-31 limited winter maint. Rwy condition report, opr wint maint 1600-2000Z‡ (DT 1500-1900Z) and 2100-0000Z‡ (DT 2000-2300Z) Sun-Fri Nov 1-Mar 31 exc statutory hols, O/T 2 hrs PN cost recovery CRFI. Ridge of high ground rises 243' AGL approximately 1 NM SE of arpt. 100' trees within 600' of rwy edge. Only pilots familiar with local terrain should use this aerodrome during hrs of darkness. Rwy 31 night operations prohibited unless PAPI and obstruction bcn serviceable. Extensive deer and geese activity invof rwy. Verify rwy unobstructed. Overnight parking on west end of apron past Twy B. Caution: Water A/D 1.4 NM S. Parking Fees.
COMMUNICATIONS: UNICOM ltd hrs OT tfc 122.7
COMM/NAV/WEATHER REMARKS: Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA). METAR 1500-0200Z‡ Oct 1-Apr 30, 1300-0000Z‡ May 1-Sep 30. OT LWIS.

• • • • •
HELIPAD H1: H69X69 (CONC)

HELIPAD H2: H69X69 (CONC)

HELIPORT REMARKS: Arr/dep on rwy, hover taxi to prkg pads.