

MAYO YT (CYMA) 1.5 N YUKON GOV'T UTC-8(-7DT) N63°37.00' W135°52.14' **WHITEHORSE**
H-1B
 1653 B NOTAM FILE CYMA Not insp.
RWY 07-25: 4843X100 (GRVL) MIRL
RUNWAY DECLARED DISTANCE INFORMATION
RWY 07: TORA-4843 TODA-5040 ASDA-4843 LDA-4843
RWY 25: TORA-4843 TODA-5040 ASDA-4843 LDA-4843
SERVICE: FUEL 100LL, JET A, Fuel avbl 1500-2200Z† Mon-Fri May 1-Sep 30, O/T call out chg 867-393-4359,
 867-335-5825 24 hr PN. **LGT** Lgt avbl to non-sked acft only.
AIRPORT REMARKS: Attended Mon-Fri. Fuel storage by permit only ctc opr. Call out charge may be levied
 for one or more svcs. Rwy 07 down 0.34%. A/D maint avbl 1400-2230Z† Mon-Fri ctc 867-383-0004. All non sked acft
 with wingspan over 60 FT require min 3 days PN. Ctc opr. **CAUTION:** Powerlines invof Rwy 07 apch. Compacted
 snow/grvl mix during winter conds. Sfc may be soft during freeze and thaw periods.
COMMUNICATIONS:
RADIO 122.1
RCO 122.375 126.7(broadcast) (WHITEHORSE RADIO)
RADIO AIDS TO NAVIGATION
NDB(BH) 365 MA N63°37.67' W135°53.71' At Fld/20E.
COMM/NAV/WEATHER REMARKS: Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada
 & USA). CARS: 867-996-234. METAR H24.

MILL BAY BC N48°40.26' W123°32.21' **SEATTLE**
L-1D, 1E
NDB(MHW) 293 MB 092° 4.6 NM to Victoria Intl./16E.

NANAIMO BC (CYCD) 7 SSE UTC-8(-7DT) N49°03.27' W123°52.20' **SEATTLE**
H-1D, 1E, L-1D, 1E
 92 B AOE NOTAM FILE CYCD Not insp.
RWY 16-34: H6602X150 (ASPH) HIRL
RWY 16: ODALS. REIL. PAPI(P2L)—GA 3.0°. Thld dsplcd 197'.
RWY 34: REIL. PAPI(P2L)—GA 3.5°. Thld dsplcd 1002'. RVR
RUNWAY DECLARED DISTANCE INFORMATION
RWY 16: TORA-6602 TODA-7094 ASDA-6602 LDA-6405
RWY 34: TORA-6602 TODA-7192 ASDA-6602 LDA-5600
SERVICE: S4 FUEL 100LL, JET A1 **LGT** After 0530Z† ACTIVATE HIRL Rwy 16-34, Rwsy 16 and 34 PAPI and REIL Rwy
 16 and Rwy 34—122.1.
AIRPORT REMARKS: Attended continuously. Fuel self svc 24 hrs, full svc Mon-Fri 1700-0100Z† OT call out avbl PN
 250-924-3639; 604-227-9274 (100LL only) Self svc 24 hrs card lock. Arpt use rstd to acft with a wingspan of less than
 118'. **CAUTION:** Recommend that only pilots familiar with local terrain should use this arpt during hrs of darkness. Ngt
 ops are not recommended unless the PAPI and all five hazard beacons are opr. ARFF services: 6 1330-0800Z (DT
 1230-0700Z) for sked acft 20 seats and abv, OT 2hr PN cost recovery. Customs avbl phone 888-226-7277. Rwy 34
 rgt hand circuts. Maintain 1200 ASL til over Ladysmith Harbour. Rwy 16 climb to a safe altitude. Left turn heading 142°
 til over Ladysmith Harbour. Climb over Harbour to 1000 ASL before proceeding on course. Avoid flgt over built up areas
 below 1000' ASL. Exty bird activity. Deer invof rwy. Twy G unlgtd, rstd daytime use only, max wt 5,000 lbs. Twy G wt
 greater than 5000 lbs PPR 250-618-0875. PAPI limitation/restriction. PAPI Rwy 34 offset 8° rgt. PAPI 34 to be used
 only within 3NM of thld. Lgts O/R FSS dur hours of ops. Hi terrain reduces operational len of Rwy 34 PAPI. OT
 ARCAL-122.1 type K. Prkg plan in effect. CBSA and corporate turbine acft must park along N edge of Apron I PPR
 250-618-0875. No exceptions. Corp turbine acft access groundside via Gate 19A only. PPR for access/egress via tml
 bldg. Remaining Apron I rstd to sked tfc only. Piston acft not permitted to use Apron I due apron congestion. Altn prkg avbl
 on Apron III ctc 604-227-9274.
COMMUNICATIONS: ATIS 128.425 1-877-517-2847 1400-0500Z (DT 1300-0400Z)
RADIO 122.1 291.8 1330-0530Z† (emerg only 250-245-4032)
GND ADV 122.6 1330-0530Z† (DT 1230-0430Z†) (emerg only 250-245-4032) (PTC avbl)
VICTORIA TRML 120.8
VICTORIA APP/DEP CON 121.075 252.3
RADIO AIDS TO NAVIGATION
NDB(BH) 251 YCD N49°07.67' W123°52.30' 163° 4.4 NM to Fld./16E.
COMM/NAV/WEATHER REMARKS: Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada
 & USA). Vancouver IFR 604-586-4590/4591, or 800-668-1333 METAR 1400-0500Z†, OT LWIS.