

CAMPBELL AIRSTRIP (CSR) PVT 4 SE UTC-9(-8DT) N61°09.52' W149°46.84'
 286 NOTAM FILE Not insp.
RWY 02-20: 5000X150 (GRVL)

ANCHORAGE
 H-1B, 2K, L-1A, 3D, 4G

RWY 02: Trees. Rgt tfc.
RWY 20: Trees.

AIRPORT REMARKS: Unattended. Parachute Jumping. Use permitted only with prior permission of BLM Anchorage field manager 267-1246, arpt manager 907-267-1357. All traffic patterns SE of fld. No winter maintenance. Rwy cond not monitored, recommend visual inspection prior to ldg. Drone use to 400' AGL.

AIRPORT MANAGER: (907) 267-1357

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE ANC.

ANCHORAGE (H) (H) VOR/DME 113.15 TED Chan 78(Y)
 N61°10.07' W149°57.61' 078° 5.2 NM to fld. 92/18E.


VOR unusable:

041°-091° byd 25 NM blo 15,000'
 091°-096° byd 20 NM blo 15,000'
 096°-121° byd 25 NM blo 12,500'
 121°-146° byd 25 NM blo 9,000'

DME unusable:

041°-091° byd 25 NM blo 15,000'
 091°-096° byd 20 NM blo 15,000'
 096°-121° byd 25 NM blo 12,500'
 121°-146° byd 25 NM blo 9,000'
 196°-206° byd 25 NM blo 3,500'
 206°-211° byd 25 NM blo 4,000'
 211°-221° byd 25 NM blo 3,500'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



CAMPBELL LAKE SPB (A11) 3 SW UTC-9(-8DT) N61°07.98' W149°56.51'
 20 NOTAM FILE A11
WATERWAY 06W-24W: 4000X200 (WATER)
WATERWAY 06W: Rgt tfc.

ANCHORAGE

SEAPLANE REMARKS: Unattended. Wind indicator: 3—pvtly maintained windsocks around the lake. Preplanned pattern to the west, unless SE wind dictates E apch/dep. No service to transient acft.

AIRPORT MANAGER: 907-269-8503

COMMUNICATIONS: CTAF 122.9

® **ANCHORAGE APP/DEP CON** 118.6 119.1 123.8 126.4