

HARPER MUNI (8K2) 1 SW UTC-6(-5DT) N37°16.69' W98°02.61'

WICHITA

1427 NOTAM FILE ICT

L-15D

RWY 17-35: H3268X38 (ASPH) HIRL

RWY 17: PAPI(P2L)—GA 3.25° TCH 57'. Tree.

RWY 35: PAPI(P2L)—GA 3.25° TCH 58'. P-line.

IAP

RWY 12-30: 2138X160 (TURF)

RWY 12: P-line.

RWY 30: P-line.

SERVICE: FUEL 100LL LGT Actvt HIRL and PAPI Rwy 17-35—CTAF.

Rwy 17 PAPI unusbl byd 3° L of cntrln.

AIRPORT REMARKS: Unattended. Credit card self-service fuel. 30° ditch AER

12. Rwy 12 marked with orange cones. Phone at field.

AIRPORT MANAGER: 620-896-2511


COMMUNICATIONS: CTAF 122.9

Ⓡ **WICHITA APP/DEP CON** 126.7

CLEARANCE DELIVERY PHONE: For CD ctc Wichita Apch at 316-350-1520.

COMM/NAV/WEATHER REMARKS: CTAF: Automated UNICOM; 3 clicks ADZY and

WX, 4 clicks radio check. ADZY also avbl by calling 617-262-3825.



HARVS N38°08.70' W97°16.57' NOTAM FILE EWK.

WICHITA

NDB (LOMW) 395 CA 174° 5.3 NM to Newton-City-Co. 1530/6E.