

WARWICK MUNI (N72) 3 NE UTC-5(-4DT) N41°17.26' W74°17.23'

NEW YORK

540 NOTAM FILE ISP

RWY 08-26: 2250X80 (TURF)

RWY 08: Tree.

RWY 26: Tree.

RWY 03R-21L: H2150X28 (ASPH) LIRL(NSTD)

RWY 03R: Tree.

RWY 21L: Trees.

RWY 03L-21R: 2100X50 (TURF)

RWY 03L: Trees.

RWY 21R: Trees.

SERVICE: FUEL 100LL LGT ACTIVATE LIRL Rwy 03R-21L—CTAF.

AIRPORT REMARKS: Attended irregularly. Arpt CLOSED to tran acft sunset-sunrise. Deer and bird act near movement areas.

Mountains and twrs in close vicinity of arpt. Self svc fuel avbl. Rwy 08 has 6' chain link fence 58' left, parallel to rwy.

Practice ldg NA. Rwy 03R-21L NSTD LIRL, spacing 400' apart. Seaplane use of Wickham Lake prohibited.

AIRPORT MANAGER: 845-258-0183

COMMUNICATIONS: CTAF/UNICOM 123.0

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448.

WATERTOWN INTL (ART)(KART) 5 W UTC-5(-4DT) N43°59.51' W76°01.17'

NEW YORK

331 B AOE ARFF Index—See Remarks NOTAM FILE ART MON Airport

H-11C, 12K, L-32F

RWY 10-28: H7001X150 (ASPH-GRVD) S-109, D-154, 2D-254

IAP, AD

PCN 43 F/C/X/T MIRL 0.3% up E

RWY 10: PAPI(P4L)—GA 3.0° TCH 47'. Trees.

RWY 28: MALSR. PAPI(P4L)—GA 3.0° TCH 45'. Trees.

RWY 07-25: H4999X150 (ASPH-GRVD) S-105, D-147, 2D-244

PCN 41 F/C/X/T HIRL 0.3% up NE

RWY 07: MALSR. PAPI(P4L)—GA 3.0° TCH 52'. Trees.

RWY 25: PAPI(P4L)—GA 3.0° TCH 44'. Trees.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 07: TORA-4999 TODA-4999 ASDA-4784 LDA-4784

RWY 10: TORA-7001 TODA-7001 ASDA-7001 LDA-7001

RWY 25: TORA-4999 TODA-4999 ASDA-4999 LDA-4999

RWY 28: TORA-7001 TODA-7001 ASDA-7001 LDA-7001

SERVICE: S4 FUEL 100LL, JET A LGT ACTVT MALSR Rwy 07; PAPI

Rwy 10 and Rwy 28; HIRL Rwy 07-25; MIRL Rwy 10-28; twy

lghts—CTAF.

AIRPORT REMARKS: Attended Oct-Apr 1100-2300Z†, May-Sept

1000-0000Z†. Deer and birds on and invof arpt. For fuel after hrs call

315-816-2331 or 315-816-2334. PPR for use of unimproved sfcs

on arpt ctc arpt manager 315-786-6002. Rwy 25 dsgnd calm wind

rwy. Wx camera avbl at WatertownAirport.com. Ngt vision device ops periodically conducted in arpt traffic pattern area.

Twy lghts not vsb under ngt vision goggles. Military helicopters training on and invof arpt. RC model acft lctd 9 NM SSW

of arpt blw 400' AGL. RC model acft act located 4 NM north of Watertown Intl Arpt blo 400' at 44.05 N-76.05 W.

Class I, ARFF Index A. PPR 2 hrs for unskd ops with more than 30 pax seats call 315-816-2334 or 315-816-2331.

Index B coverage is avbl O/R. Rwy/Twy conditions not monitored outside of normal attendance hrs. Acft de/anti icing avbl,

ctc FBO 315-786-6001. Ldg fee for acft over 6000 lbs gross weight. 2 hrs advance notice to U.S. Cstrms by pilot rqrd,

call 315-482-2261.

AIRPORT MANAGER: 315-786-6002

WEATHER DATA SOURCES: ASOS 132.325 (315) 639-4002. (WX CAM)

COMMUNICATIONS: CTAF/UNICOM 123.0

RCO 122.2 (BURLINGTON RADIO)

RCO 122.1R 109.8T (BURLINGTON RADIO)

Ⓡ **WHEELER-SACK APP/DEP CON** 124.875

CLNC DEL 120.8

CLEARANCE DELIVERY PHONE: For CD if una to ctc Wheeler Sack ATCT on freq, ctc Wheeler Sack ATCT at 315-772-7105.

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE ART.

(L) (L) VORTAC 109.8 ART Chan 35 N43°57.13' W76°03.88' 051° 3.1 NM to fld. 374/12W.

VOR unusable:

090°-111° byd 15 NM

112°-150°

151°-175° byd 20 NM

ILS 111.1 I-ART Rwy 07. Class ID. Autopilot cpd apch na blw 900'.

