

PATRICK LEAHY BURLINGTON INTL (See BURLINGTON on page 330)**POST MILLS** (2B9) 0 E UTC-5(-4DT) N43°53.02' W72°15.13'

NEW YORK

696 NOTAM FILE BTV

RWY 04-22: 2900X80 (TURF)**RWY 04:** Trees. Rgt tfc.**RWY 22:** Road.**RWY 05-23:** 2300X80 (TURF) 0.8% up NE**RWY 05:** Trees. Rgt tfc.**RWY 23:** Road.**SERVICE:** S2**AIRPORT REMARKS:** Attended irregularly. Ultralights; gliders and hot air balloons on and in/ovf arpt. Trees 200' from end of Rwys 22 and 23. 60' trees directly adjacent to runway edge, left. Uniform width and length of Runways 05-23 is 2,200' 80'.

Non-std turf cones placement-do not use delineate actual thlds-all rwys. Acft ops counts unavailable. No snow removal.

Arpt open to ski acft only when snow covered. Call 802-333-9254 for info. Propane avbl for hot air balloons.

AIRPORT MANAGER: 802-333-9254**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.**RUTLAND/SOUTHERN VERMONT RGNL** (RUT)(KRUT) 5 S UTC-5(-4DT) N43°31.78'

NEW YORK

W72°56.98'

H-11D, 12K, L-32G

787 B Class IV, ARFF Index A NOTAM FILE RUT

IAP

RWY 01-19: H5304X100 (ASPH-GRVD) S-40, D-68, 2S-86

PCN 30 F/D/X/U MIRL

RWY 01: PVASI(PSIR)—GA 3.5° TCH 17'. Thld dspcd 300'. Hill.**RWY 19:** MALSR. PAPI(P4L)—GA 3.2° TCH 55'. Rgt tfc.**RWY 13-31:** H3169X75 (ASPH) S-30 PCN 5 F/D/X/U MIRL**RWY 13:** REIL. Road.**RWY 31:** Trees.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 01:** TORA-5303 TODA-5303 ASDA-5303 LDA-5003**RWY 19:** TORA-5003 TODA-5003 ASDA-5003 LDA-5003**SERVICE:** S4 FUEL 100LL, JET A LGT ACTVT MALSR Rwy 19; REIL Rwy 13; MIRL Rwy 01-19 and 13-31—CTAF. Rwy end 01: VGSI OTS UFN.**NOISE:** Noise sensitive area SE of arpt ctc amgr.**AIRPORT REMARKS:** Attended 1200-0100Z±. Birds on and in/ovf arpt. For

aft hrs svc call 802-773-3348. Rwy conditions may not be

monitored or reported when the arpt is unattended. Rwy 13-31 not

avbl for skedd acf ops (ldgs and tkof) more than 9 pax seats or

unskd acf ops at least 31 pax seats. Avbl for acf ops taxi only. Clsd

to unskd acf ops with more than 9 pax seats exc 48 hr PPR, call

amgr 802-786-8881. Use Twy A to tax to or from AER 01 or 19. Twy C connects main apn with Twy A. Acft with wing

spans exceeding 79 ft auzd to use Twy H & Twy B east of Rwy 01-19 & Rwy 13-31 for tax & Rwy 01 & 19 for tkof &

ldg. Type I and type IV deicing avbl. Cold temperature airport. Altitude correction required at or below -8C. Ldg fees may

apply for coml acft.

AIRPORT MANAGER: 802-585-5586**WEATHER DATA SOURCES:** AWOS-3PT 118.375 (802) 747-3044.**COMMUNICATIONS:** CTAF/UNICOM 122.8

RCO 122.3 (BURLINGTON RADIO)

Ⓡ **BOSTON CENTER APP/DEP CON** 135.7**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RUT.**SMUTO NDB (MHW)** 221 DYO N43°42.37' W72°57.40' 193° 10.6 NM to fld. 1138/15W.

NDB unusable:

351°-189° byd 15 NM

ILS/DME 111.7 I-RUT Chan 54 Rwy 19. Class IA. Glideslope unusable byd 4.00° right of course.