

COLLEGE PLACE

MARTIN FLD (S95) 1 W UTC-8(-7DT) N46°02.82' W118°25.03'

SEATTLE

750 NOTAM FILE SEA

L-13A

RWY 05-23: H3819X60 (ASPH) S-12 LIRL(NSTD)**RWY 05:** VASI(V2L).**RWY 23:** VASI(V2R). Road.**SERVICE:** S2 **FUEL** 100LL **LGT** Rwy 05-23 NSTD LIRL southwest 1240' medium ints. Arpt lgtg opr from dusk until 1000Z. **ACTIVATE** NSTD LIRL Rwy 05-23 and VASI Rwy 05 and Rwy 23—CTAF.**AIRPORT REMARKS:** Attended Mon-Fri 1600-0100Z. Call in advn 509-386-0000. 24 hr self svc credit card fueling facility. Gliders and other acft perform ops on turf btn Rwy 05-23 and twy. Overnight parking fee of \$3.00. Pvt road crosses 700' from southwest end of rwy. 2/3 of the rwy has wdspr, opn, unsealed cracks and joints, hi lvl of raveling and alligator cracking. Ldg fee.**AIRPORT MANAGER:** 509-386-0000**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Spokane Apch at 509-742-2525, when Apch clsd ctc Seattle ARTCC at 253-351-3694.**RADIO AIDS TO NAVIGATION:** NOTAM FILE ALW.**WALLA WALLA (VL) (DH) VOR/DME** 116.4 ALW Chan 111 N46°05.22' W118°17.55' 231° 5.7 NM to fld. 1150/14E.

VOR unusable:

016°-071° byd 31 NM blo 12,500'

032°-042° byd 40 NM blo 12,500'

032°-042° byd 62 NM

042°-169° byd 40 NM

071°-101° byd 20 NM blo 14,500'

101°-146° byd 20 NM blo 13,500'

256°-285° byd 40 NM

286°-296° byd 40 NM blo 4,000'

286°-296° byd 50 NM

291°-302° byd 40 NM

309°-319° byd 40 NM blo 4,000'

309°-319° byd 85 NM

320°-031° byd 40 NM

DME unusable:

071°-101° byd 20 NM blo 14,500'

116°-071° byd 31 NM blo 12,500'

146°-151° byd 20 NM blo 11,500'

COLVILLE MUNI (63S) 1 E UTC-8(-7DT) N48°32.65' W117°53.01'

SEATTLE

1888 B NOTAM FILE SEA

RWY 01-19: H2695X40 (ASPH) S-11 MIRL**RWY 19:** Tree.**SERVICE:** **FUEL** 100LL **LGT** Dusk-dawn. **ACTIVATE** MIRL Rwy 01-19—CTAF.**AIRPORT REMARKS:** Attended Mon-Fri 1600-0100Z. Watch for deer on and invof arpt. Rwy 19 dthr 255'. When ldg Rwy 19, bright lgts around high school stadium, aprx 3/4 miles south of arpt. Ocnl vehicular tfc across end of Rwy 01-19 and twy. Grass ldg area avbl across Rwy 01-19 1500'X150'. Hazards are 50' obst on both ends, trees/poles. Apron and tiedown grvl; 3 asph paved transient tiedowns westside. Eastside tiedowns gravel. 2 car avbl.**AIRPORT MANAGER:** 509-685-9056**WEATHER DATA SOURCES:** AWOS-3 119.275 (509) 684-8994.**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

CONCRETE

MEARS FLD (3W5) 1 S UTC-8(-7DT) N48°31.79' W121°45.49'

SEATTLE

267 NOTAM FILE SEA

RWY 07-25: H2609X60 (ASPH) S-12**RWY 07:** Trees. Rgt tfc.**RWY 25:** Trees.**SERVICE:** **FUEL** 100LL**AIRPORT REMARKS:** Unattended. Elk and deer freq both rwy ends and mid-fld. All patterns south of arpt.**AIRPORT MANAGER:** 425-322-8582**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.• • • • •
HELIPAD H1: H40X40 (CONC)**HELIPORT REMARKS:** Helipad for emerg use only.