

CONTINUED FROM PRECEDING PAGE

RADIO AIDS TO NAVIGATION: NOTAM FILE BOI.

BOISE (VH) (H) VORTACW 113.3 BOI Chan 80 N43°33.17' W116°11.53' 303° 23.5 NM to fld. 2877/17E.

VOR unusable:

001°-044° byd 22 NM blo 11,000'
 001°-044° byd 32 NM blo 14,500'
 023°-033° byd 40 NM blo 15,500'
 023°-033° byd 50 NM blo 18,000'
 034°-081° byd 40 NM
 045°-071° byd 32 NM blo 12,500'
 072°-084° byd 32 NM blo 10,500'
 082°-092° byd 40 NM blo 11,500'
 082°-092° byd 53 NM blo 14,000'
 082°-092° byd 71 NM blo 18,000'
 093°-107° byd 40 NM
 108°-118° byd 40 NM blo 9,500'
 108°-118° byd 56 NM
 119°-210° byd 40 NM
 211°-221° byd 40 NM blo 9,400'
 211°-221° byd 52 NM
 222°-233° byd 40 NM
 273°-283° byd 40 NM blo 6,000'
 273°-283° byd 69 NM blo 9,000'
 273°-283° byd 88 NM
 284°-295° byd 40 NM

TACAN AZIMUTH unusable:

010°-060° byd 12 NM blo 13,000'
 010°-060° byd 27 NM blo 15,500'
 113°-155° byd 30 NM blo 7,000'
 348°-010° byd 20 NM blo 13,000'
 348°-010° byd 27 NM blo 15,500'

DME unusable:

010°-060° byd 12 NM blo 13,000'
 010°-060° byd 27 NM blo 15,500'
 113°-155° byd 30 NM blo 7,000'
 348°-010° byd 20 NM blo 13,000'
 348°-010° byd 27 NM blo 15,500'

VOR unusable:

296°-309° byd 40 NM blo 5,500'
 296°-309° byd 46 NM blo 9,000'
 296°-309° byd 84 NM blo 18,000'
 315°-022° byd 40 NM

FAIRFIELD

FROSTENSON FLD (U86) 0 S UTC-7(-6DT) N43°20.51' W114°47.90'

SALT LAKE CITY

5058 NOTAM FILE BOI

RWY 08-26: 2950X40 (DIRT)

RWY 08: Road. Rgt tfc.

RWY 26: Pole.

AIRPORT REMARKS: Unattended. Irregular winter maintenance and snow removal, check rwy condition before using.

AIRPORT MANAGER: (208) 720-9020

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

FISH LAKE (USFS) (S92) 0 E UTC-8(-7DT) N46°19.81' W115°03.79'

GREAT FALLS

5646 NOTAM FILE BOI

RWY 05-23: 2650X50 (TURF)

RWY 05: Tree.

RWY 23: Trees.

AIRPORT REMARKS: Unattended. No winter maintenance. Rwy 05-23 soft when wet. Elk wallows on rwy. Land Rwy 23, tkf Rwy 05. No touch and go ldgs or stop and go ldgs, go arounds not recommended due to steep rising terrain off west end of Rwy 05-23. Rwy 05-23 additional 400' of length avbl for tkf on the end of Rwy 05. Down drafts prevalent over lake. Ctc USFS arpt manager 208-983-9677 for briefings and rwy conditions. Recommend early morning and late evening ops during summer months. Normally mowed to a usable width of 50'-75'. Rwy 23 end marked with concrete T marker and large w cones. Rwy 05 end marked with large w cones. No telephone avbl at arpt.

AIRPORT MANAGER: 208-983-9677

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.