

FORT WORTH

BOURLAND FLD (50F) 17 SW UTC-6(-5DT) N32°34.91' W97°35.45'

873 B NOTAM FILE FTW

Rwy 17-35: H4049X60 (ASPH) MIRL 0.9% up N

Rwy 17: VASI(V2L)—GA 3.0° TCH 23'. Thld dsplcd 392'. Road.

Rwy 35: VASI(V2L)—GA 3.5° TCH 28'. Thld dsplcd 215'. Trees.

SERVICE: FUEL 100LL, JET A LGT ACTVT MIRL Rwy 17-35—CTAF.

VASI Rwys 17 and 35 opr consly.

AIRPORT REMARKS: Attended Mon-Sat dalgt hrs. For svcs aft hrs call 817-752-4701. Deer on and invof rwy. 100LL self serve. Arprt clsd to tsnt student tfc. Arprt clsd to acft ovr 12,500 lb max GWT. Rwy hold short lines NSTD 25 ft fm rwy edge.

AIRPORT MANAGER: 817-752-4701

COMMUNICATIONS: CTAF/UNICOM 123.0

® **REGIONAL APP/DEP CON** 135.975

CLEARANCE DELIVERY PHONE: For CD ctc Regional Apch at 972-615-2799.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

MILLSAP (VH) (H) VORTACW 117.7 MQP Chan 124 N32°43.57' W97°59.85' 104° 22.3 NM to fld. 900/9E.

VOR unusable:

004°-009° byd 40 NM

010°-054° byd 40 NM blo 3,800'

010°-054° byd 46 NM blo 5,000'

010°-054° byd 56 NM

055°-066° byd 40 NM blo 3,800'

055°-066° byd 50 NM

230°-247° byd 40 NM

248°-258° byd 40 NM blo 3,700'

248°-258° byd 53 NM

259°-270° byd 40 NM blo 6,000'

259°-270° byd 63 NM

271°-285° byd 40 NM

312°-316° byd 40 NM

325°-340° byd 40 NM blo 3,000'

325°-340° byd 46 NM blo 5,000'

325°-340° byd 66 NM

353°-003° byd 40 NM blo 18,000'

DALLAS-FORT WORTH
COPTER
L-17C, A
IAP

