

HAYFORK (F62) 1 S UTC-8(-7DT) N40°32.82' W123°10.78'
 2334 B NOTAM FILE RIU
RWY 07-25: H4100X60 (ASPH) S-12.5 MIRL 0.4% up E

KLAMATH FALLS
 L-2H

RWY 07: Tree.

RWY 25: Tree. Rgt tfc.

SERVICE: S2 LGT Arpt bcn OTS indef. MIRL Rwy 07-25 OTS. ACTIVATE MIRL Rwy 07-25—CTAF.

NOISE: Noise abatement procedures in effect N, NE and S of arprt.

AIRPORT REMARKS: Unattended. High terrain all quadrants. Intermittently clsd winters due to snow. Ctc county transportation office for information 530-623-1365.

AIRPORT MANAGER: 530-623-1365

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

RADIO AIDS TO NAVIGATION: NOTAM FILE FOT.

FORTUNA (L) (L) VORTACW 114.0 FOT Chan 87 N40°40.28'
 W124°14.07' 079° 48.8 NM to fld. 392/19E.

VOR unusable:

060°-070° byd 35 NM blo 9,500'

150°-165° byd 25 NM blo 6,500'

165°-200° byd 25 NM blo 8,000'

280°-330° byd 20 NM blo 3,000'

330°-336° byd 20 NM

336°-350° byd 20 NM blo 3,000'

TACAN AZIMUTH unusable:

060°-070° byd 35 NM blo 9,500'

150°-165° byd 25 NM blo 5,500'

165°-200° byd 25 NM blo 8,000'

315°-325° byd 15 NM blo 5,500'

DME unusable:

060°-070° byd 35 NM blo 9,500'

150°-165° byd 25 NM blo 5,500'

165°-200° byd 25 NM blo 8,000'

315°-325° byd 15 NM blo 5,500'

