

CORONA N34°22.02' W105°40.68' NOTAM FILE ABQ.

ALBUQUERQUE
H-4L, 6F, L-6F

(VH) (H) **VORTAC** 115.5 CNX Chan 102 046° 28.0 NM to Vaughn Muni. 6412/13E.

VOR unusable:

019°-029° byd 40 NM
043°-056° byd 40 NM blo 11,000'
043°-056° byd 62 NM
064°-089° byd 40 NM
102°-114° byd 40 NM blo 9,000'
102°-114° byd 48 NM
115°-135° byd 35 NM blo 10,000'
115°-148° byd 40 NM
149°-159° byd 40 NM blo 14,000'
149°-159° byd 65 NM
160°-170° byd 40 NM
172°-182° byd 40 NM blo 14,000'
172°-182° byd 65 NM

DME unusable:

115°-135° byd 35 NM blo 10,000'
135°-185° byd 20 NM blo 12,000'
185°-205° byd 20 NM blo 13,000'
205°-260° byd 20 NM blo 14,000'

TACAN AZIMUTH unusable:

115°-119° byd 25 NM blo 10,000'
119°-121°
121°-135° byd 25 NM blo 10,000'
135°-185° byd 20 NM blo 12,000'
185°-205° byd 20 NM blo 13,000'
205°-215°
215°-245° byd 20 NM blo 14,000'
245°-260°

RCO 122.1R 115.5T (ALBUQUERQUE RADIO)

CROWNPOINT (ØE8) 3 NW UTC-7(-6DT) N35°43.06' W108°12.10'

DENVER
H-4K, L-8H

6696 B NOTAM FILE ABQ

RWY 18-36: H5820X60 (ASPH) PCN 3 F/D/Y/T MIRL

RWY 18: PVASI(PSIL)—GA 3.0° TCH 40'.

SERVICE: LGT ACTIVATE MIRL Rwy 18-36—122.9.

AIRPORT REMARKS: Unattended. Rwy 18 and Rwy 36 markings and centerline faded or missing.

AIRPORT MANAGER: 505-371-8354

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE GUP.

GALLUP (VH) (H) VORTAC 115.1 GUP Chan 98 N35°28.56' W108°52.36' 052° 35.9 NM to fld. 7053/14E.

VOR unusable:

298°-306° byd 40 NM

CUBA LANDING STRIP (NM2) 4 S UTC-7(-6DT) N35°57.11' W106°57.45'

DENVER

6840 NOTAM FILE ABQ

RWY 06-24: 4137X40 (DIRT)

RWY 06: Brush.

RWY 24: Brush.

AIRPORT REMARKS: Unattended. Livestock, elk and deer on or in/ovf arpt. Rwy 06-24 surface 2-4 in scattered rock and 3-5 in rutts due to vehicle t/c on rwy.

AIRPORT MANAGER: 505-761-8797

COMMUNICATIONS: CTAF 122.9

COMM/NAV/WEATHER REMARKS: Use CTAF within 5 NM of arpt.