

ESPAÑOLA**OHKAY OWINGEH** (E14) 3 NE UTC-7(-6DT) N36°01.57' W106°02.72'**DENVER**
H-4L, 6F, L-8I

6100 NOTAM FILE ABQ

RWY 16-34: H5007X75 (ASPH) S-18 PCN 7 F/D/Y/T MIRL**RWY 16:** Thld dsplcd 324'.**SERVICE:** FUEL 100LL, JET A1+ LGT ACTVT MIRL Rwy 16-34—CTAF.**AIRPORT REMARKS:** Unattended. 100LL fuel H24 with credit card. Wildlife on and invof arpt. Main gate locked—aces 4751.

Rwy 16 dthr not mkd. Rwy 16-34 1.5 in deep 2-4 in wid cracks acrs rwy ev 50-100 ft. 7083 ft MSL twr 3.3 NM 010 degs N of arpt.

AIRPORT MANAGER: 505-692-3345**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.**RADIO AIDS TO NAVIGATION:** NOTAM FILE SAF.**SANTA FE (L) (L) VORTACW** 110.6 SAF Chan 43 N35°32.43' W106°03.90' 349° 29.1 NM to fld. 6268/13E.

VORTAC unusable:

015°-030° byd 30 NM blo 14,600'

ESTANCIA MUNI (E92) 1 E UTC-7(-6DT) N34°45.80' W106°02.48'**ALBUQUERQUE**

6100 NOTAM FILE ABQ

RWY 08-26: 4000X50 (GRVL)**RWY 08:** Pole.**RWY 26:** Brush.**SERVICE:** LGT Rwy 08 markings NSTD, thld and edge marked with reflective material. Several reflectors missing and reflective material in poor cond. Rwy 26 markings NSTD, thld and edge marked with reflective material. Several reflectors missing and reflective material in poor cond.**AIRPORT REMARKS:** Unattended. Cattle and birds on and invof rwy. Rwy 08-26 soft when wet. Rwy 08 +12' tree 134' from thld, 78' rgt of cntrln. Rwy 26 +3-5' brush 0-200' from thld, 125' left and rgt of cntrln. Rwy 08-26 scattered brush in primary surface, +2-3 ft high, 30-40 ft fm cntrln both sides.**AIRPORT MANAGER:** 505-401-3701**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.