

VENETIE (VEE)(PAVE) 1 E UTC-9(-8DT) N67°00.52' W146°21.98'
574 B NOTAM FILE FAI

FAIRBANKS
H-1B, L-4J
IAF

RWY 04-22: 4000X75 (GRVL) MIRL

RWY 04: Road.

RWY 22: Trees.

SERVICE: LGT ACTIVATE MIRL Rwy 04-22 and rot bcn—CTAF. Rotating bcn OTS indef. Twy lghts OTS indef.

AIRPORT REMARKS: Unattended. Maint in winter variable. Rwy 04-22 sfc slippery when wet, sfc uneven and sparsely graveled. Rwy 04 road transits rwy approximately 300' from thld. PPR before landing phone 907-849-8165. Construction equipment and persons operating on and in/ovf rwy.

AIRPORT MANAGER: 907-849-8165

COMMUNICATIONS: CTAF 122.9

Ⓡ **ANCHORAGE CENTER APP/DEP CON** 135.0

RADIO AIDS TO NAVIGATION: NOTAM FILE FYU.

FORT YUKON (H) (H) VORTACW 114.4 FYU Chan 91 N66°34.46'
W145°16.60' 296° 36.8 NM to fld. 449/20E.

VOR unusable:

001°-360° byd 15 NM

249°-259° byd 10 NM blo 4,900'


TACAN AZIMUTH unusable:

280°-300° byd 35 NM blo 2,500'

DME unusable:

280°-300° byd 35 NM blo 2,500'

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.



VISNAW LAKE SPB (See WASILLA on page 258)

WAINWRIGHT

WAINWRIGHT (AWI)(PAWI) 1 SE UTC-9(-8DT) N70°38.28' W159°59.69'

CAPE LISBURNE
H-1A, L-4I
IAF

45 B NOTAM FILE AWI

RWY 06-24: 4494X110 (GRVL) MIRL

RWY 06: REIL. PAPI(P4L)—GA 3.0° TCH 31'. Antenna.

RWY 24: REIL. PAPI(P4R)—GA 3.0° TCH 30'.

SERVICE: LGT ACTVT REIL Rwy 06 and Rwy 24, PAPI Rwy 06 and Rwy 24, MIRL Rwy 06-24—CTAF.

AIRPORT REMARKS: Unattended. Rwy cond unmnt; rcmd visual insp prior to use. Rwy 06-24, 40 ft twr 500 ft N of rwy. Birds on and in/ovf arpt. Ramp and twy sfc soft; ruts and ponding psbl. NOTE: See Notices—Drone Activity at Coastal Airport Launch Sites.

AIRPORT MANAGER: 907-852-0489

WEATHER DATA SOURCES: ASOS 132.25 (907) 763-8881. (WX CAM)

COMMUNICATIONS: CTAF 122.8


WAINWRIGHT RCO 122.5 (BARROW RADIO)

ANCHORAGE CENTER APP/DEP CON 135.3

RADIO AIDS TO NAVIGATION: NOTAM FILE AWI.

NDB (HW) 338 UKK N70°38.26' W160°00.56' at fld.
38/12E.

COMM/NAV/WEATHER REMARKS: Barrow FSS—1-800-779-7709. Local call to Barrow FSS dial 907-852-2511. For a toll free call to Fairbanks dial 1-866-248-6516.



WAINWRIGHT AS (AKØ3)(PAWT) PVT 0 N UTC-9(-8DT) N70°36.80' W159°51.62'

CAPE LISBURNE
L-4I

35 B NOTAM FILE BRW Not insp.

RWY 03-21: 3000X100 (GRVL) MIRL

RWY 03: REIL. Rgt tfc.

RWY 21: REIL.

SERVICE: LGT Bcn on consly.

AIRPORT REMARKS: CLOSED to public; Bureau of Land Management (BLM) facility. Caution: Rwy not mntnd; rcmd visual insp prior to ldg. Mult soft spots; dirt & grvl on rwy.

AIRPORT MANAGER: (907) 382-4199

COMMUNICATIONS: CTAF 126.2