39

ALEKNAGIK MISSION STRIP (4AK7) PVT 1 NE UTC-9(-8DT) N59°16.86′ W158°35.83′

KODIAK

150 NOTAM FILE

RWY 09-27: 1500X35 (GRVL)

RWY 09: Tree/bushes. RWY 27: Tree/bushes.

RWY 03-21: 1400X25 (GRVL-DIRT)

AIRPORT REMARKS: Unattended. No maintenance, unusable during winter months. Climb out from rwy very steep.

AIRPORT MANAGER: 907-242-4173

COMMUNICATIONS: CTAF 122.9

COMM/NAV/WEATHER REMARKS: Dillingham FSS Local call 842-5275. For a toll free call to Kenai FSS dial 1-866-864-1737.

TRIPOD (Z25) 2 SE UTC-9(-8DT) N59°15.79′ W158°33.47′

KODIAK

225 NOTAM FILE DLG

RWY 11-29: 1250X50 (TURF-GRVL)

RWY 11: Trees.

RWY 29: Trees.

RWY 18-36: 850X40 (GRVL-DIRT)

RWY 18: Trees.

RWY 36: Trees.

AIRPORT REMARKS: Unatndd. Rwys not maintained; recommend prior inspection before use. Rwy 18-36 has 7' trees growing in the center of the rwy midfield. Rwy unusable for fixed wing acft. Rwy 11 forest with 32' trees 0' from threshold. Rwy 36 forest across entire apch up to 0 of threshold. No rwy markings either rwy. Rwy 11-29 is very rough and overgrown with brush and trees. Rwy 11-29 sfc consists of a narrow ATV trail and undulating tundra which slopes downhill towards north. Rwy 18-36 surface is very uneven and occasionally very soft. Rwy 18-36 used as an ATV camping site. Rwy 18-36 unusable only 10 ft wide with 6-12 ft trees encroaching & rocks to 10 inches on sfc.

COMMUNICATIONS: CTAF 122.9

ALITAK SPB (See LAZY BAY on page 161)

ALL WEST (See DELTA JUNCTION on page 93)