

CRYSTAL FALLS

IRON CO (50D) 6 SE UTC-6(-5DT) N46°00.54' W88°16.44'
1340 NOTAM FILE GRB

GREEN BAY

L-31A

RWY 12-30: H3690X50 (ASPH) LIRL(NSTD)

RWY 12: Trees.

RWY 30: Trees.

RWY 02-20: 2700X145 (TURF) 0.4% UP N

RWY 02: Trees.

RWY 20: Tree.

SERVICE: LGT Actvt NSTD LIRL Rwy 12-30—121.7. Rwy 12-30
NSTD LIRL due to 36 ft fm rwy edge.

AIRPORT REMARKS: Unattended. Deer and birds on and invof arpt. No snow
removal. Arpt clsd Nov 15-Apr 15 and when snow covd exc for ski
equipped acft. Rwy 12-30 nmrs cracks and vegetation in pavement.
Twy and ramp areas in poor cond- nmrs cracks and vegetation in
pavement. Rwy 02 and Rwy 20 mkg type: 3 ft yellow cones.

AIRPORT MANAGER: 906-265-6144

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD etc Minneapolis ARTCC at
651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE IMT.

IRON MOUNTAIN (L) (L) VORW/DME 111.2 IMT Chan 49

N45°48.96' W88°06.73' 332° 13.4 NM to fld. 1129/2W.

DME unusable:

020°-140° blo 10,000'


140°-195° byd 30 NM blo 2,900'

140°-195° byd 35 NM blo 4,000'

141°-220° byd 20 NM blo 2,900'

221°-315° byd 15 NM blo 4,000'

316°-019° byd 20 NM blo 5,000'



CUSTER (See MONROE on page 222)

DALTON (See FLUSHING on page 186)

DELTA CO (See ESCANABA on page 184)

DENTON FARMS (See CLARE on page 172)