

## LINCOLN

**MILWRICK FLYING M** (3L7) 3 NE UTC-5(-4DT) N44°44.30' W83°22.78'

LAKE HURON

830 NOTAM FILE LAN

**RWY 09-27:** 2200X90 (TURF)

**RWY 09:** Thld dspclcd 600'. Pole.

**RWY 27:** Trees.

**AIRPORT REMARKS:** Attended May-Oct irregularly. Arpt CLOSED Nov-Apr and when snow covd. Deer and lrg brids on and invof arpt. No snow removal. Arpt access gate locked, for access call amgr. Rwy 09-27 soft in spring, sfc rough and ireg on rolling trrn. Downslope fm west to east. Rwy 09 and dthr marked with 3' yellow cones. Rwy 09 p-line marked with yellow balls.

**AIRPORT MANAGER:** 989-736-1098

**COMMUNICATIONS:** CTAF/UNICOM 123.0

**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.

## LINDEN

**PRICES** (9G2) 1 S UTC-5(-4DT) N42°48.46' W83°46.14'

919 B NOTAM FILE LAN

**RWY 09-27:** H3999X75 (ASPH) MIRL 0.3% up W

**RWY 09:** REIL. Thld dspclcd 267'. Trees.

**RWY 27:** Thld dspclcd 800'. Trees.

**SERVICE:** S2 FUEL 100LL LGT Actvt REIL Rwy 09; MIRL Rwy 09-27-CTAF.

**AIRPORT REMARKS:** Attended ireg. Deer & lrg birds on & invof arpt. Airframe repairs: prior arrangement.

**AIRPORT MANAGER:** 586-946-5381

**COMMUNICATIONS:** CTAF/UNICOM 123.0

**FLINT RCO** 122.3 (LANSING RADIO)

Ⓡ **GREAT LAKES APP/DEP CON** 128.55 (1030-0500Z±)

Ⓡ **CLEVELAND CENTER APP/DEP CON** 126.75 (0500-1030Z±) ctc Cleveland ARTCC at 440-774-0229.

**CLEARANCE DELIVERY PHONE:** For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0229/0490.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE FNT.

**FLINT (VH) (H) VORTACW** 116.9 FNT Chan 116 N42°58.01' W83°44.82' 192° 9.6 NM to fld. 771/6W.

TACAN AZIMUTH unusable:

174°-184° wi 15 NM

229°-309° byd 30 NM

310°-228° blo 10,000'

VOR unusable:

070°-090° byd 40 NM

100°-125° byd 40 NM

145°-203° byd 40 NM

223°-233° byd 40 NM

Byd 30 NM blo 3,000'

DME unusable:

174°-184° wi 15 NM


Byd 30 NM blo 3,000'

DETROIT

COPTER

L-28J

IAP



**LIVINGSTON CO SPENCER J HARDY** (See HOWELL on page 202)