

CROSBY MUNI (D50) 1 N UTC-6(-5DT) N48°55.70' W103°17.85'

BILLINGS

1950 B NOTAM FILE GFK

L-13E, 14F

RWY 12-30: H3800X60 (ASPH) S-12.5 MIRL

RWY 12: PAPI(P2L)—GA 3.0° TCH 22'.

RWY 30: PAPI(P2L)—GA 3.0° TCH 23'. Acft.

RWY 03-21: 2680X100 (TURF) 0.3% up SW

RWY 03: Road.

RWY 21: Road.

SERVICE: FUEL 100LL LGT PAPI Rwy 12 and Rwy 30 ops dusk-0700Z†. MIRL Rwy 12-30 preset on low ints dusk-0700Z†, to increase ints ACTIVATE—CTAF. After 0700Z† ACTIVATE MIRL Rwy 12-30 and PAPI Rwy 12 and Rwy 30—CTAF.

AIRPORT REMARKS: Unattended. 24 hr self svc avbl with credit card. Rwy 03-21 CLOSED winter months due to lack of snow removal. Deer and birds on and in/ovf arpt. Rwy 03-21 daylight cone markers only.

AIRPORT MANAGER: 701-570-0944

WEATHER DATA SOURCES: AWOS-3 118.025 (701) 965-6732.


COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE ISN.

WILLISTON (VL) (DH) VOR/DME 116.3 ISN Chan 110

N48°15.20' W103°45.04' 016° 44.4 NM to fld. 2365/8E.



DEERING N48°24.92' W101°21.97' NOTAM FILE MIB.

BILLINGS

(H) TACAN 114.9 MIB Chan 96 1654/7E.

H-2H, L-14F

No NOTAM MP: 1530-1730Z† Wed (1500/3+1)

TACAN AZ unusable:

294°-304° byd 13 NM blo 5,000'

294°-304° byd 21 NM

DME unusable:

294°-304° byd 13 NM blo 5,000'

294°-304° byd 21 NM