

LANGDON

ROBERTSON FLD (D55) 1 WSW UTC-6(-5DT) N48°45.19' W98°23.63'

TWIN CITIES

1608 B NOTAM FILE GFK

L-14G

RWY 14-32: H3600X60 (ASPH) S-12.5 MIRL

IAP

RWY 14: PAPI(P2L)—GA 3.0° TCH 28'.**RWY 32:** PAPI(P2L)—GA 3.0° TCH 27'.**RWY 08-26:** 1930X100 (TURF)**RWY 26:** Road.**SERVICE:** FUEL 100LL LGT Actvt PAPI rwy 14 and rwy 32; MIRL rwy 14-32—CTAF.**NOISE:** Noise sensitive area NW quadrant of field, avoid overflight.**AIRPORT REMARKS:** Attended on call. Large birds and deer on and invof arpt for svcs after hrs ctc arpt manager

701-370-9710. Self svc fuel avbl 24 hr with credit card. Rwy 08-26 CLSD winters due to lack of snow removal. Confirm winter conds/snow removal with arpt manager at 701-370-9710. Apr-Nov. Midfield N/S twy is clsd indef due to poor condition. Cold temperature airport. Altitude correction required at or below -35C.

AIRPORT MANAGER: (701) 370-9710**WEATHER DATA SOURCES:** AWOS-3 118.225 (701) 256-2121.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓜ **MINNEAPOLIS CENTER APP/DEP CON** 132.15**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DVL.**DEVILS LAKE (DH) DME** 114.75 DVL Chan 94(Y) N48°06.91' W98°54.75' 028° 43.5 NM to fld. 1448.**LARIMORE MUNI** (2L1) 1 W UTC-6(-5DT) N47°54.40' W97°38.46'

TWIN CITIES


1130 NOTAM FILE GFK

RWY 12-30: H2914X50 (ASPH) S-4 LIRL**RWY 12:** Rgt tfc.**RWY 30:** Thld dspld 87'. Road.**SERVICE:** LGT SS-SR.**AIRPORT REMARKS:** Attended Mon-Sat on call. Snow removal irregular Oct thru May. For conditions report ctc arpt manager at 701-343-2065 or cell 218-779-4244.**AIRPORT MANAGER:** 218-779-4244**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**LEEDS MUNI** (D31) 2 E UTC-6(-5DT) N48°17.10' W99°24.13'

TWIN CITIES

1508 NOTAM FILE GFK

L-14G

RWY 09-27: H3000X50 (ASPH) S-7**RWY 27:** Road.**AIRPORT REMARKS:** Unattended. Confirm winter conditions and snow removal after major storms call arpt manager 701-740-7309. Migratory waterfowl on and invof arpt Apr-May and Sep-Nov. Rwy 09-27 has 600' lgtd turf stopway west end.**AIRPORT MANAGER:** 406-581-1188**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DVL.**DEVILS LAKE (DH) DME** 114.75 DVL Chan 94(Y) N48°06.91' W98°54.75' 298° 22.1 NM to fld. 1448.**LIDGERWOOD MUNI** (4N4) 1 NW UTC-6(-5DT) N46°05.38' W97°09.97'

TWIN CITIES

1082 NOTAM FILE GFK

RWY 18-36: 2100X60 (TURF)**RWY 36:** Brush.**AIRPORT REMARKS:** Unattended. Addl contact-chair aprt auth 701-640-1568. Airport closed in winter months due to no snow removal. Birds and deer on and invof arpt. Rwy wid 60' in areas with steep drop-offs into water.**AIRPORT MANAGER:** 701-899-1155**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.