

PHILIP (PHP)(KPHP) 3 E UTC-7(-6DT) N44°02.92' W101°35.93'

CHEYENNE

2209 B NOTAM FILE PHP

L-12G

RWY 12-30: H3998X75 (ASPH) S-12.5 MIRL 0.4% up NW

RWY 12: PAPI(P2L)—GA 3.0° TCH 31' . Pole.

RWY 30: PAPI(P2L)—GA 3.0° TCH 27' .

RWY 05-23: 3588X120 (TURF)

RWY 23: Tree.

SERVICE: FUEL 100LL LGT ACTIVATE PAPI Rwy 12 and Rwy 30, MIRL

Rwy 12-30—CTAF.

AIRPORT REMARKS: Unattended. Fuel avbl 24 hrs with credit card. Rwy 05-23 marked with black/white cones. Rwy 12 VGSJ and RNAV glidepath not coincident. Rwy 30 VGSJ and RNAV glidepath not coincident.

AIRPORT MANAGER: 605-859-2175

WEATHER DATA SOURCES: ASOS 118.375 (605) 859-2065.

COMMUNICATIONS: CTAF/UNICOM 122.8

RCO 122.4 (HURON RADIO)

Ⓡ DENVER CENTER APP/DEP CON 127.95

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Denver ARTCC at 303-651-4257.


RADIO AIDS TO NAVIGATION: NOTAM FILE PHP.

(L) (L) VOR/DME 108.4 PHP Chan 21 N44°03.49'

W101°39.85' 089° 2.9 NM to fld. 2340/12E.

VOR unusable:

250°-325° byd 30 NM blo 4,500'



PIERRE RGNL (PIR)(KPIR) 3 E UTC-6(-5DT) N44°22.96' W100°17.16'

OMAHA

1744 B ARFF Index—See Remarks NOTAM FILE PIR MON Airport

H-2I, L-12H

RWY 13-31: H6900X100 (ASPH-GRVD) S-91, D-108, 2S-137,

2D-168 PCN 51 F/C/W/T HIRL

RWY 13: REIL. PAPI(P4L)—GA 3.0° TCH 52' .

RWY 31: MALSR. PAPI(P4L)—GA 3.0° TCH 55' .

RWY 07-25: H6880X150 (ASPH-GRVD) S-91, D-114, 2S-145,

2D-180 PCN 58 F/C/W/T HIRL 0.6% up W

RWY 07: REIL. PAPI(P4L)—GA 3.0° TCH 46' . Tank.

RWY 25: REIL. PAPI(P4L)—GA 3.0° TCH 53' .

RUNWAY DECLARED DISTANCE INFORMATION

RWY 07: TORA-6880 TODA-6880 ASDA-6830 LDA-6830

RWY 13: TORA-6900 TODA-6900 ASDA-6900 LDA-6900

RWY 25: TORA-6880 TODA-6880 ASDA-6880 LDA-6880

RWY 31: TORA-6900 TODA-6900 ASDA-6900 LDA-6900

SERVICE: S4 FUEL 100LL, JET A 0X1, 2, 3, 4 LGT ACTIVATE MALSR

Rwy 31; REIL Rwy 07, Rwy 13 and Rwy 25; PAPI Rwy 07, Rwy 25,

Rwy 13 and Rwy 31; HIRL Rwy 07-25 and Rwy 13-31—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1100-0600Z, Sat-Sun

1100-0400Z. Birds on and in/ovr apt and within a 25 NM radius. For

attendant other times call 605-224-9000/8621. Arpt cond

unmonitored during 0400-1200Z Mon-Fri, 1900Z Sat to 1900Z

Sun. No line of sight between rwy ends of Rwy 07-25. Class I, ARFF

Index B. 48 hr PPR for unscheduled acft ops involving acft designed for 31 or more passenger seats call 605-773-7447

or 605-773-7405. Taxiway C is 50' wide and restricted to acft 75,000 pounds or less. Air carrier landing fee, \$14 +

\$1 per 1000 lbs over 20k lbs. NOTE: See Special Notices Section—Aerobatic Practice Areas.

AIRPORT MANAGER: 605-773-7447

WEATHER DATA SOURCES: ASOS 119.025 (605) 224-6087.

COMMUNICATIONS: CTAF 122.7 UNICOM 122.95

RCO 122.2 (HURON RADIO)

Ⓡ MINNEAPOLIS CENTER APP/DEP CON 125.1

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Minneapolis ARTCC at 651-463-5588.

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE PIR.

(VL) (H) VORTACW 113.75 PIR Chan 84(Y) N44°23.67' W100°09.77' 251° 5.3 NM to fld. 1791/11E.

VOR unusable:

005°-016° byd 40 NM blo 10,000'

005°-016° byd 88 NM

017°-023° byd 40 NM

ILS/DME 111.9 I-PIR Chan 56 Rwy 31. Class IA.

