

**DANIELSON** (LZD)(KLZD) 2 NW UTC-5(-4DT) N41°49.19' W71°54.06'

NEW YORK

238 B NOTAM FILE BDR

L-33C, 34J

RWY 13-31: H2700X75 (ASPH) S-29 MIRL

IAP

RWY 13: Tree.

RWY 31: REIL. Tree.

SERVICE: S4 FUEL 100LL LGT ACTVT REIL Rwy 31; MIRL Rwy 13-31—CTAF.

AIRPORT REMARKS: Unattended. Parachute Jumping. Extsv paja SR-SS May-Oct. Gldr actvy on &amp; invof arpt. Deer on &amp; invof arpt. Self svc fuel, credit card rqrd: Visa, Mastercard. Ldg fee for business, corporate &amp; revenue producing acft.

AIRPORT MANAGER: 860-982-2443

WEATHER DATA SOURCES: AWOS-3 119.125 (860) 779-7251.

COMMUNICATIONS: CTAF/UNICOM 123.0

Ⓡ PROVIDENCE APP/DEP CON 123.675 (Sun-Fri 1030-0530Z±, Sat 1030-0500Z±) other times ctc  
 BOSTON CENTER APP/DEP CON 124.85


CLEARANCE DELIVERY PHONE: For CD ctc Providence Apch at 401-738-8945, when Apch clsd ctc Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE BDR.

PUTNAM (H) (H) VORW/DME 117.4 PUT Chan 121 N41°57.33' W71°50.65' 211° 8.5 NM to fld. 652/14W.

DME unusable:

265°-301° byd 36 NM blo 3,000'

**EAST HADDAM****GOODSPEED** (42B) 1 SE UTC-5(-4DT) N41°26.74' W72°27.34'

NEW YORK

9 NOTAM FILE BDR

RWY 14-32: H2120X50 (ASPH) S-8 LIRL

RWY 32: Trees.

SERVICE: S4 LGT Arpt lgts opr 24 hrs.

AIRPORT REMARKS: Unattended. Caution deer, birds and waterfowl on and invof arpt. Parl turf twy mkd with yellow cones. May be soft when wet or aft rain. Seaplane dock and ramp. Overnight parking fee. Ldg fee.

AIRPORT MANAGER: (860) 615-9068

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2449.

WATERWAY 16W-34W: 4500X1000 (WATER)

WATERWAY 16W: Bridge.

WATERWAY 34W: Hill.

**ELLINGTON** (7B9) 2 N UTC-5(-4DT) N41°55.53' W72°27.43'

NEW YORK

253 NOTAM FILE BDR

RWY 01-19: H1800X50 (ASPH) S-9 RWY LGTS(NSTD)

RWY 01: Trees.

RWY 19: Trees.

SERVICE: S4 FUEL 100LL LGT Non-std LIRL opr dusk-0500Z±, for lgts aft 0500Z± call 860-871-2054 durg bus hrs. Rwy 01-19 non-std LIRL due to spacing, thr lgts outboard of rwy.

AIRPORT REMARKS: Attended 1300-2300Z±. Parachute Jumping. Extensive helicopter training ops. Acft tfc pat on E side of arpt only. Hel tfc pat on W side of arpt only. Twy pavement failed, extsv cracking, patches, loose aggregate and sml stones. Rwy 01 mkg faded. Rwy 19 mkg faded.

AIRPORT MANAGER: 860-614-1854

COMMUNICATIONS: CTAF/UNICOM 123.0

CLEARANCE DELIVERY PHONE: For CD ctc Yankee Apch at 860-386-3597.

**FARMINGTON** CT71 N41°42.54' W72°48.13' /363

NEW YORK

AWOS-AV 129.825 AWOS-AV wx bcst on 129.825 (3 mic clicks).

L-33C, 34I

**GOODSPEED** (See EAST HADDAM on page 35)