WASHINGTON

BADGER MOUNTAIN N47°35.29′ RCO 122.3 (SEATTLE RADIO)	W120º08.60′		SEATTLI L—1D, 9/
BANDERA STATE (4WØ) 0 W 1636 NOTAM FILE SEA RWY 08-26: 2344X100 (TURF) RWY 08: Trees. RWY 26: Trees.	UTC-8(-7DT)	N47°23.72′W121°32.19′	SEATTLI
AIRPORT REMARKS: Unattended. Arpt Rwy 08–26 west end extremely State Aviation Division 360–70	rough, rwy soft v 9–8015 or 1–80 emergency opera	when wet. Vehicles, pedestrians 0–552–0666 WA area for facili	ic safety/law enforcement helicopter ops. s and animals on and invof rwy. Ctc WA ity info prior to use. For acft wy marked with reflectors dur dates arpt
CLEARANCE DELIVERY PHONE: For CD v	when ATCT is clso	d ctc Seattle Apch at 206-214-	4722.
ATTLE GROUND CEDARS NORTH (W58) 1 NW 275 NOTAM FILE SEA RWY 08-26: 1960X50 (TURF) RWY 08: Trees. RWY 26: Trees. Alepend Remarks: Linattended Bird	UTC-8(-7DT)	N45°45.87′ W122°30.91′	SEATTLI
from thid. Rwy and twy soft in v Airport Manager: 360-687-8234 Communications: CTAF 122.9 Clearance Delivery Phone: For CD c	winter.		
292 NOTAM FILE SEA	 3(–7DT) N45°	49.61′ W122°34.61′	SEATTLI
SERVICE: S4 LGT Rwy 15 NSTD V AIRPORT REMARKS: Attended continue	ously. Rwy 07–2 incline. Rwy 25 6 Hngrs 61 ft and	5 for emerg only. Rwy 15–33 w 6 ft fence, 16 ft from rwy end. Re 67 ft fm edge of Rwy 07.	TIVATE LIRL Rwy 15–33—CTAF. vidth of 43' over culvert in center of fld. oad intersects Rwy 07–25 at mid–point.