

LUBBI N33°39.76' W101°43.39' NOTAM FILE LBB.
 NDB (LOMW) 272 LD 265° 4.9 NM to Lubbock Preston Smith Intl. 3198/6E.

DALLAS–FT. WORTH

LUBBOCK

LUBBOCK EXEC AIRPARK (F82) 5 S UTC-6(-5DT) N33°29.03' W101°48.78'
 3176 B NOTAM FILE FTW

DALLAS–FT WORTH
H-6G, L-6H

RWY 17-35: H5144X70 (CONC-TRTD) S-13 HIRL

RWY 17: Thld dsplcd 58'.

RWY 35: Thld dsplcd 385'.

RWY 07-25: 1524X110 (TURF) 0.5% up W

RWY 07: P-line.

SERVICE: S4 FUEL 100LL, JET A1+

AIRPORT REMARKS: Attended 1300-0300Z±, after hrs 806-440-6210. 100LL and Jet A1+ full serv durg atnidd hrs;
 self-serve 24 hrs. Farm equip oprs AER 17, 25, 35. Rwy 07-25 35 ft trees alg N rwy edge. Rwy 07-25 rwy rough with
 bare spots. Rwy defined by mowing. No by mkg.

AIRPORT MANAGER: 806-745-4967

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE LBB.

(L) (L) **VORTACW** 109.2 LBB Chan 29 N33°42.30' W101°54.84' 148° 14.2 NM to fld. 3310/11E.

VOR unusable:

040°-050° byd 38 NM blo 5,300'

210°-260° byd 25 NM blo 6,000'