

**ROANOKE RAPIDS**

**HALIFAX/NORTHAMPTON RGNL** (IXA)(KIXA) 8 S UTC-5(-4DT) N36°19.79' W77°38.11'

WASHINGTON

H-9C, 12H, L-35C, 36G  
IAP

144 B NOTAM FILE IXA

**RWY 02-20:** H5500X100 (ASPH) S-45, D-65 HIRL

**RWY 02:** REIL. PAPI(P2L)—GA 3.0° TCH 25'. Trees.

**RWY 20:** MALSR. PAPI(P2L)—GA 3.0° TCH 24'. Trees.

**SERVICE:** FUEL 100LL, JET A1+ LGT Actvt MALSR Rwy 20; REIL

Rwy 02; PAPI Rwy 02 & 20; HIRL Rwy 02-20—CTAF.

**AIRPORT REMARKS:** Attended Mon-Sat 1300-2200Z, Sun 1700-2200Z. For svc after hrs contact 252-578-3774. Unattended New Years Day, Easter, Jul 4th, Thanksgiving, and Christmas. Birds on & invof arpt. Agriculture equip ocny adj to Rwy 02-20. 100LL and Jet-A fuel avbl 24 hrs self service w/ credit card.

**AIRPORT MANAGER:** 252-583-3492

**WEATHER DATA SOURCES:** AWOS-3PT 119.975 (252) 583-3446.

**COMMUNICATIONS:** CTAF/UNICOM 123.075

Ⓡ WASHINGTON CENTER APP/DEP CON 132.025

**CLEARANCE DELIVERY PHONE:** For CD ctc Washington ARTCC at 703-771-3587.


**RADIO AIDS TO NAVIGATION:** NOTAM FILE RDU.

**TAR RIVER (VL) (H) VORTAC** 117.8 TYI Chan 125 N35°58.60' W77°42.22' 014° 21.4 NM to fld. 73/5W.

VOR unusable:

253°-257° byd 40 NM

299°-318° byd 40 NM



**ROCKINGHAM**

**RICHMOND CO** (RCZ)(KRCZ) 3 S UTC-5(-4DT) N34°53.48' W79°45.58'

CHARLOTTE

H-9C, 12H, L-25E, 35A, 36E  
IAP

358 B NOTAM FILE RCZ

**RWY 14-32:** H5001X100 (ASPH) S-30 MIRL

**RWY 14:** PAPI(P2L)—GA 3.0° TCH 24'. Thld dsplcd 150'. Trees.

**RWY 32:** REIL. PAPI(P2L)—GA 3.0° TCH 40'. Thld dsplcd 201'. Railroad.

**RWY 04-22:** 3009X490 (TURF) 0.3% up SW

**RWY 04:** Trees.

**RWY 22:** Trees.

**SERVICE:** FUEL 100LL, JET A1+ LGT Actvt dusk-dawn. REIL Rwy 32; PAPI Rwy 14 and 32; MIRL Rwy 14-32—CTAF.

**AIRPORT REMARKS:** Attended Mon-Fri 1300-2200Z, unatndd Sat, Sun and Federal Hols. For arpt attendant nights and Sun call 910-997-5071. 100LL and Jet A—24hr self-service with credit card. Rwy 04-22 not in use when wet—turbine engine acft and acft over 10,000 lbs. Call 910-997-5071 for runway conditions before landing. Rwy 14 has 60' drop-off 350' from dsplcd thr all sides. Rwy 32 has numerous obstructions in apch including 5' fence, 12' road, and 20' railroad.

**AIRPORT MANAGER:** 910-206-0419

**WEATHER DATA SOURCES:** AWOS-3 118.775 (910) 997-4093.

**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ FAYETTEVILLE APP/DEP CON 127.8

**CLEARANCE DELIVERY PHONE:** For CD ctc Washington ARTCC at 703-771-3587.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE RDU.

**SANDHILLS (L) (L) VORTAC** 111.8 SDZ Chan 55 N35°12.93' W79°35.28' 207° 21.2 NM to fld. 588/3W.

VOR unusable:

075°-143°

144°-154° blo 6,000'

144°-154° byd 23 NM

155°-179° blo 5,000'

180°-264° blo 8,000'


301°-019° byd 10 NM blo 10,000'

DME unusable:

041°-092° blo 3,000'

TAC AZM unusable:

016°-050° byd 28 NM blo 3,000'



**ROCKINGHAM CO HELIPORT** (See EDEN on page 308)