

ERICK**HADDOCK FLD** (O13) 1 SW UTC-6(-5DT) N35°12.05' W99°52.86'

DALLAS-FT WORTH

2097 NOTAM FILE MLC

RWY 17-35: H2650X35 (ASPH) S-4

SERVICE: LGT Bcn OTS indefly.

AIRPORT REMARKS: Unattended. Military helicopter traffic on and infov arpt. Svr cracking and grass encroachment.

AIRPORT MANAGER: (580) 243-9190

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

EUFAULA**EUFAULA MUNI** (F08) 2 W UTC-6(-5DT) N35°17.90' W95°37.64'

DALLAS-FT WORTH

635 B NOTAM FILE MLC

L-15E

RWY 17-35: H3000X60 (ASPH) S-4 MIRL 0.4% up N

RWY 17: PAPI(P2L)—GA 3.5° TCH 46'. Trees.

RWY 35: PAPI(P2L)—GA 3.5° TCH 45'. Tree.

SERVICE: FUEL 100LL LGT MIRL Rwy 17-35 preset low ints, to incr ints, ACTIVATE—CTAF.

AIRPORT REMARKS: Unattended. Ultralghts on and infov arpt. 100LL 24 hr self-service.


AIRPORT MANAGER: 918-689-2534

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE MLC.

MC ALESTER (L) TACAN Chan 57 MLC (112.0) N34°50.97' W95°46.94' 008° 28.0 NM to fld. 782/8E.

**FOUNTAINHEAD LODGE AIRPARK** (ØF7) 6 N UTC-6(-5DT) N35°23.32' W95°36.02'

DALLAS-FT WORTH

670 NOTAM FILE MLC

L-15E

RWY 18-36: H3000X50 (ASPH) S-8

RWY 36: Tree.


SERVICE: LGT MIRL OTS indef.

AIRPORT REMARKS: Unattended. Deer on and infov rwy.

AIRPORT MANAGER: 918-689-5311

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

**FAIRMONT FLD** (10K) 2 NE UTC-6(-5DT) N36°21.91' W97°40.07'

WICHITA

1170 NOTAM FILE Not insp.

RWY 17-35: 2540X65 (TURF) 0.3% up S

SERVICE: FUEL MOGAS

AIRPORT REMARKS: Unattended. Wildlife on and infov arpt. 4 ft seasonal crops at both apch ends Rwy 17-35. Ldg fee.

AIRPORT MANAGER: 580-242-6627

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Vance Apch at 580-213-6765. When Vance Apch is clsd, ctc Kansas City ARTCC at 913-254-8508.