

GROVETON—TRINITY CO (33R) 3 NW UTC-6(-5DT) N31°05.06' W95°09.85'

HOUSTON
L-19E, 21A

340 B NOTAM FILE CXO

RWY 16-34: H3500X60 (ASPH) S-8 LIRL

RWY 16: Trees.

RWY 34: Trees.

SERVICE: LGT ACTIVATE LIRL Rwy 16-34—CTAF.

AIRPORT REMARKS: Unattended. Deer and feral hogs on and invof arpt.

AIRPORT MANAGER: 936-642-1746

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

RADIO AIDS TO NAVIGATION: NOTAM FILE LFK.

LUFKIN (VH) (H) VORTACW 112.1 LFK Chan 58 N31°09.75' W94°43.01' 254° 23.5 NM to fld. 207/5E.

TACAN AZIMUTH unusable:

260°-275° byd 30 NM

275°-260° byd 30 NM blo 2,500'

DME unusable:

260°-275° byd 30 NM

275°-260° byd 30 NM blo 2,500'

VOR unusable:

305°-312° byd 40 NM

313°-323° byd 40 NM blo 2,300'

313°-323° byd 66 NM

324°-330° byd 40 NM

GRUVER MUNI (E19) 2 SW UTC-6(-5DT) N36°14.02' W101°25.93'

WICHITA
L-15B

3205 B NOTAM FILE FTW

RWY 02-20: H4698X60 (ASPH) S-12.5 MIRL 0.4% up SW

RWY 02: Fence.

SERVICE: LGT Actvt MIRL Rwy 02-20—CTAF.

AIRPORT REMARKS: Unattended. Extsv pavement cracking, potholes at Rwy 20 thr. Rwy 02 and Rwy 29 mkgs faded.

AIRPORT MANAGER: 806-733-2424

COMMUNICATIONS: CTAF 122.9

® ALBUQUERQUE CENTER APP/DEP CON 127.85

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

RADIO AIDS TO NAVIGATION: NOTAM FILE BGD.

BORGER (L) TACAN Chan 23 BGD (108.6) N35°48.42' W101°22.93' 344° 25.7 NM to fld. 3130/11E.

TACAN AZIMUTH unusable:

220°-320° byd 10 NM blo 12,000'

GUADALUPE PASS N31°49.97' W104°48.55'

EL PASO
L-6B

RCO 122.5 (ALBUQUERQUE RADIO)

GUTHRIE VUF N33°38.23' W100°20.86'/1787

DALLAS—FT WORTH
L-17B

AWOS-3PT 120.20 (806) 596-4616 VUF AWOS-3PT is associated with 6666 Ranch airport 6TE6.

GUTHRIE N33°46.70' W100°20.17' NOTAM FILE FTW.

DALLAS—FT. WORTH
H-6G, L-17B

(L) DME 114.5 GTH Chan 92 010° 15.2 NM to Dan E Richards Muni. 1941.

H H COFFIELD RGNL (See ROCKDALE on page 410)

HALE CO (See PLAINVIEW on page 401)

HALL—MILLER MUNI (See ATLANTA on page 253)