

KLAWOCK (AKW)(PAKW) 2 NE UTC-9(-8DT) N55°34.75' W133°04.56'**KETCHIKAN**

80 B NOTAM FILE AKW

H-1D, L-1C

RWY 02-20: H5000X100 (ASPH-GRVD) D-100 MIRL 0.8% up NE

IAP

RWY 02: REIL. PAPI(P4L)—GA 3.0° TCH 34'. Road.**RWY 20:** REIL. PAPI(P4L)—GA 4.0° TCH 40'. Road. Rgt tfc.**SERVICE:** LGT ACTVT PAPI Rwy 02 and 20, MIRL Rwy 02-20, windsock, apron lghts—122.25. ACTVT rotating bcn—CTAF. Rwy 20 PAPI unusbl byd 3 degs left of cntrln.**AIRPORT REMARKS:** Unattended. Birds and wildlife on and invof arpt. Rpt bird act to Amgr or FSS. High trrn all quads. Rcmd daylight ops only. Rwy 02-20 slopes down 55-65 ft fm thrs to cntr. Exp downdraft and turb invof Rwy 02 TDZ. Irregular wind conditions. CLOSED to actv over 12500 lbs GWT, exc PPR—Amgr. CLOSED to acr ops more than 30 pax seats. Cond unmnt, maint ireg, rcmd visual insp bfr use. PAJA on rwy, twy and parking apron NA. Rwy 20 700 ft hill 2 mi NE of thr. Cold temperature airport. Altitude correction required at or below -9C.**AIRPORT MANAGER:** 907-755-2229**WEATHER DATA SOURCES:** ASOS 135.45 (907) 755-2641. (WX CAM)**COMMUNICATIONS:** CTAF 120.9

RCO 122.25 (KETCHIKAN RADIO)

② **ANCHORAGE CENTER APP/DEP CN 118.5****RADIO AIDS TO NAVIGATION:** NOTAM FILE SIT.**LEVEL ISLAND (H) (H) VORW/DME 116.5** LVD Chan 112 N56°28.06' W133°04.99' 160° 53.4 NM to fld. 98/20E.

VOR unusable:

020°-050° byd 37 NM

270°-300° byd 25 NM blo 10,000'

301°-321° byd 25 NM blo 7,000'

wx cam avbl at <https://weathercams.faa.gov>

DME unusable:

020°-050° byd 25 NM blo 11,000'

020°-050° byd 37 NM

105°-120° byd 29 NM blo 10,000'

121°-135° byd 35 NM blo 7,000'

270°-300° byd 25 NM blo 10,000'

301°-321° byd 25 NM blo 7,000'

345°-350° byd 36 NM blo 8,000'

(H) HW/DME 115.8 AKW Chan 105 N55°34.12' W133°04.88' at fld. 52. NOTAM FILE AKW.

DME unusable:

034°-189° blo 8,000'

304°-354° blo 8,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Ketchikan FSS dial 800-478-3500. For a LC to Juneau FSS dial 789-7380.**KOBUK** (OBU)(PAOB) 0 N UTC-9(-8DT) N66°54.74' W156°53.84'**FAIRBANKS**

142 B NOTAM FILE OTZ

H-2A, L-41

RWY 09-27: 4020X75 (GRVL) MIRL

IAP

RWY 09: Brush.**RWY 27:** Brush.**SERVICE:** LGT ACTIVATE MIRL Rwy 09-27—CTAF.**AIRPORT REMARKS:** Unattended. Rwy condition not monitored, recommend visual inspection prior to ldg. Float plane opr on lake. Dip on Rwy 09 abeam slough. Parallel p-line north of rwy. Cold temperature airport. Altitude correction required at or below -37C.**AIRPORT MANAGER:** 907-442-3147**COMMUNICATIONS:** CTAF 122.7

AMBLER RCO 122.0 (KOTZEBUE RADIO)

② **ANCHORAGE CENTER APP/DEP CN 119.2****RADIO AIDS TO NAVIGATION:** NOTAM FILE OTZ.**KOTZEBUE (H) (H) VORW/DME 115.7** OTZ Chan 104 N66°53.14'

W162°32.40' 072° 133.4 NM to fld. 121/15E.

AMBLER NDB (HW) 403 AMF N67°06.31'

W157°51.61' 102° 25.5 NM to fld. 258/15E. NOTAM FILE

AFM.

COMM/NAV/WEATHER REMARKS: For LC to Kotzebue FSS dial 907-442-3310. For a toll free call to Kotzebue FSS dial 1-800-478-7460. For a toll free call to Fairbanks FSS dial 1-866-248-6516.