

**PERRY ISLAND SPB** (PYL) 0 S UTC-9(-8DT) N60°41.12' W147°55.12'

ANCHORAGE

00 NOTAM FILE JNU

**WATERWAY N-S:** 10000X2000 (WATER)

**COMMUNICATIONS:** CTAF 122.9

**RADIO AIDS TO NAVIGATION:** NOTAM FILE JNU.

**JOHNSTONE POINT (H) (H) VOR/DME** 116.7 JOH Chan 114 N60°28.86' W146°35.96' 270° 40.9 NM to fld.  
48/18E.

wx cam

VOR unusable:

090°-124° byd 23 NM blo 8,000'

125°-188° byd 10 NM

DME unusable:

090°-124° byd 23 NM blo 12,000'

125°-191° byd 10 NM

**PERRYVILLE** (PEV)(PAPE) 1 SSW UTC-9(-8DT) N55°54.40' W159°09.65'

COLD BAY

30 B NOTAM FILE ENA

L-2K

**RWY 02-20:** 3300X75 (GRVL) MIRL

**RWY 02:** REIL. PAPI(P4L)—GA 3.4° TCH 28'. Hill.

**RWY 20:** Hill.

**SERVICE:** LGT ACTVT REIL Rwy 02; PAPI Rwy 02; MIRL Rwy 02-20 and rotating bcn—CTAF.

**AIRPORT REMARKS:** Unattended. Rwy cond not monitored; rcmd visual inspection prior to using. Rwy 02-20 several ruts.

**AIRPORT MANAGER:** 907-246-3325

**WEATHER DATA SOURCES:** AWOS-3P 118.1 (907) 269-2843. (WX CAM)

**COMMUNICATIONS:** CTAF 122.9

® **ANCHORAGE CENTER APP/DEP CON** 125.35

**RADIO AIDS TO NAVIGATION:** NOTAM FILE SDP.

**BORLAND NDB/DME (HW)** 390 HBT Chan 79 N55°18.94'  
W160°31.10' 041° 58.3 NM to fld. 130/11E.

NDB unusable:

304°-354° byd 16NM

DME unusable:

034°-134° byd 6NM

184°-264° byd 27 NM blo 14,000'

184°-264° byd 6 NM blo 10,000'

354°-034° byd 22 NM blo 18,000'

354°-034° byd 27NM

354°-034° byd 6 NM blo 10,000'

**COMM/NAV/WEATHER REMARKS:** For a local call to Cold Bay FSS dial 1-800-478-7250. For a toll free call to Kenai FSS dial 1-866-864-1737.

