

POINT BAKER SPB (KPB)(PFKP) 0 SE UTC-9(-8DT) N56°21.11' W133°37.36'

JUNEAU

00 NOTAM FILE SIT

WATERWAY N-S: 4000X250 (WATER)

SEAPLANE REMARKS: Attended daylight. Narrow and congested opr area, small islands both entrances to core. Boats tied to SPB/helicopter float/ramp. Seaplane float designed to support 22,000 lbs maximum GWT helicopters. Float deteriorated, be alert when loading near capacity.

AIRPORT MANAGER: (907) 465-4512**COMMUNICATIONS:** CTAF 122.9**RADIO AIDS TO NAVIGATION:** NOTAM FILE SIT.


LEVEL ISLAND (H) (H) VORW/DME 116.5 LVD Chan 112
N56°28.06' W133°04.99' 229° 19.3 NM to fld. 98/20E.

VOR unusable:

020°-050° byd 37 NM
270°-300° byd 25 NM blo 10,000'
301°-321° byd 25 NM blo 7,000'
wx cam avbl at <https://weathercams.faa.gov>

DME unusable:

020°-050° byd 25 NM blo 11,000'
020°-050° byd 37 NM
105°-120° byd 29 NM blo 10,000'
121°-135° byd 35 NM blo 7,000'
270°-300° byd 25 NM blo 10,000'
301°-321° byd 25 NM blo 7,000'
345°-350° byd 36 NM blo 8,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Sitka FSS dial 1-800-478-6300.**POINT HOPE** (PHO)(PAPO) 2 SW UTC-9(-8DT) N68°20.89' W166°47.95'

CAPE LISBURNE

21 B NOTAM FILE PHO

H-1A, L-4H

RWY 03-21: H4000X75 (ASPH) MIRL

IAP

RWY 03: PAPI(P4R)—GA 3.0° TCH 25'.**RWY 21:** PAPI(P4L)—GA 3.0° TCH 25'.**SERVICE:** LGT ACTVT PAPI Rwy 03-21; MIRL Rwy 03-21—CTAF.

AIRPORT REMARKS: Unattended. Rwy cond unmt, rcmd visual insp prior to Indg. Fuel avbl emerg only. 1-3 in cracks acrs width spaced 200-500 ft entr length. NOTE: See Notices—Drone Activity at Coastal Airport Launch Sites.

AIRPORT MANAGER: 907-442-3147**WEATHER DATA SOURCES:** AWOS-3P 118.325 (907) 368-2128. (WX CAM)**COMMUNICATIONS:** CTAF 122.8**POINT HOPE RCO** 122.25 (KOTZEBUE RADIO)**ANCHORAGE CENTER APP/DEP CON** 119.65 363.25**RADIO AIDS TO NAVIGATION:** NOTAM FILE LUR.

CAPE LISBURNE NDB/DME (HW) 385 LUR Chan 20(Y) N68°52.28'
W166°04.56' 200° 35.3 NM to fld. 61/7E.

NDB has no standby transmitter, May be shutdown without prior notice

NDB unusable:

141°-169° byd 20 NM

DME unusable:

004°-129° byd 20 NM

129°-291° byd 5 NM blo 9,000'

COMM/NAV/WEATHER REMARKS: For a LC to Kotzebue FSS dial 907-442-3310. For a toll free call to Kotzebue FSS dial 1-800-478-7460. For a toll free call to Fairbanks FSS dial 1-866-248-6516.

