AI ASKA

WILLOW SPB (2X2) 1 NW UTC-9(-8DT) N61°44.61′ W150°03.58′

ANCHORAGE

**FAIRBANKS** 

200 NOTAM FILE ENA

WATERWAY 13W-31W: 3600X400 (WATER)

SERVICE: S7

SEAPLANE REMARKS: Unattended. Acft run-up area at the NE end of lake is marked by buoys seasonally. No public dock avbl. GrvI public ramp lctd on NE shore of lake. No public parking avbl. Major power plant repairs avbl. No winter maintenance be alert during Idg/tkf. A buov has been placed aprx 200' from the most southern point of land on the southeast end of the lake. Acft opr are not allowed inside the 200' marker unless taxiing to or from the shore, or taxiing to the acft run-up area. Pilots should be aware of watercraft and recreational activities on the lake. A visual inspection prior to ldg is recommended. Wind indicator avbl at Willow Arpt across the road. Buoys are removed from lake prior to freeze-up and replaced when lake thaws. It is recommended that all acft tkf toward the south, weather conditions permitting. No east/west tkf or ldg are permitted.

AIRPORT MANAGER: 907-495-6286

COMMUNICATIONS: CTAF/UNICOM 122.8

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai ESS dial 1-866-864-1737

0.7% up NE

## WINGSONG ESTATES (See DELTA JUNCTION on page 94)

WISEMAN (WSM) 1 SSW UTC-9(-8DT) N67°24.31′ W150°07.25′ 1195 NOTAM FILE FAI

RWY 02-20: 2000X30 (TURF-DIRT) RWY 02: Thid dsplcd 500'. Trees.

RWY 20: Trees. Rgt tfc.

AIRPORT REMARKS: Unattended, Rwv not maintained and condition not monitored, recommend visual inspection prior to landing. Be Alert: Backcountry strip in mountain valley, high terrain all quadrants. Recommend dog leg approach Rwy 02 due to hill. Windsock may be unreliable due to obstruction by trees. Trees to 35' within 75' each side of rwy centerline. 6 inch rocks and 24 inch grass along rwy sfc, 48 inch saplings in Rwy 02 safety area. Rwy 02-20 marked with reflective markers and cones. Ski plane ops only in winter, snow removal not avbl.

AIRPORT MANAGER: 907-451-2207 COMMUNICATIONS: CTAF 122 9

RADIO AIDS TO NAVIGATION: NOTAM FILE WCR

CHANDALAR LAKE NDB (HW) 263 CQR N67°30.14' 240° 38.6 NM to fld. 1875/22E, NDB W148°28.16′ unmonitored

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.

0000000 0 0 0 0 <del>0 0</del> G G G , G G G © C3 9999999 000 G G 03 03 90 00 G<sup>CI</sup> €3 C C C C €3 લાવા વૃ €3 (3 <sub>(3</sub> 63 ુત લ લ લે • ପ୍ର ୯ C3 C3 000000 o oo' G G ්රැ රැ 03 03 03 €3 43 0 0 0 0 €3 €3 G (3 Q3 Q3 C3 C3 Δž 0 0 0 0 G G C C C C Ø ¢3 €3 €3 43 240° 38.6 NM From €3 Chandalar Lake "CQR" NDB

WOLF LAKE (See PALMER on page 195)

RC0 122.2 (KENAI RADIO)

WOODY ISLAND N57°46.49′ W152°19.48′ NOTAM FILE ADQ. NDB (HW) 394 RWO 241° 5.6 NM to Kodiak. 24/14E.

KUDIAK

H-1B, 2K, L-2J, 3D