

**EARECKSON AS** (SYA)(PASY) AF 0 S UTC-10(-9DT) N52°42.74' E174°06.82'

98 B NOTAM FILE PASY Not insp.

**RWY 10-28:** H10004X150 (ASPH-GRVD) PCN 132F/A/W/T HIRL**RWY 10:** ALSF1. PAPI(P4L)—GA 2.5° TCH 45'. Rgt tfc.**RWY 28:** SALSF. PAPI(P4L)—GA 2.5° TCH 49'.**W ALEUTIAN ISLS**

H-2H, L-2H

DIAP, AD

**ARRESTING GEAR/SYSTEM****RWY 10** MB100 (B) 1850 FT.BAK12(B) 4450 FT. **RWY 28****SERVICE:** LGT Arpt has rglr & LED obstn lgt; LED lgt may not be vsb to ngt vision devices. ACTVT ALSF1 Rwy 10; SALSF

Rwy 28, HIRL Rwy 10-28—CTAF. PAPI Rwy 10 and Rwy 28 opr consly.

**MILITARY REMARKS:** Attended Mon-Fri 1800-0300Z† (0800-1700 local), clsd wkend and hol. USAF installation; clsd to civ ops. Mil/civ declared emerg & in distress will be honored. RCR/RSC same as atndd hr. FICON and rwy cond code not rptrd.

ARFF Index 7C. 7 day site arr or 45 day foreign natnl req—D317-552-5020/5107/C907-552-5020/5107 and

PPR—D317-392-3505/3606/4005/C907-392-3505/3606/4005. Svc fee rqrd. Tran svc Mon-Fri 1800-0300Z†; clsd

wkend and hol. Aft hr may incur O/T and svc fee. Mandatory and info signs not installed. Hvy goose actvt Apr-Jun and

Aug-Oct; gulls &amp; ravens invof arpt. Rpt bird/wildlife strikes on or invof Eareckson—EAS Aflld Ops/twr

D317-392-3505/C907-392-3505 and 11AF/SE D317-552-4730/C907-552-4730. Flts originating outside the

United States refer to AK section of USAF—Foreign Clnc Guide. 30 min PN for barrier svc. **CAUTION:** Illusion of hgt & usbl

rwy wid psbl lndg durg low vsby &amp; at ngt. Non std VFR pat Rwy 10. Twy A, D and pri HCP clsd. Alt HCP 72 hr PPR. Hills

8 NM west 662' MSL. Rwy 10-28 with 25' shoulders. **CAUTION:** Rwy 10-28 200' turn radius max; tow bar and psnl

for lrg coml acft rqrq gtr than 200' turnaround NA. No overun; sheer drop offs. Coord ETOP or aflld

criteria—D317-392-3362/C907-392-3362. Unctld arpt; prac apch, fleet svc, customs and acft maint NA deicer SAE

AMS 1424P Type 1 avbl with 1 hr PN. Civil acft lndg permit req 30 days bfr ldg—D317-552-0424/C907-552-5282.

NOTE: See General Notices—Radiation Areas.

**AIRPORT MANAGER:** 907-392-3362**COMMUNICATIONS:** CTAF 127.2① **ANCHORAGE CENTER APP/DEP CON** 119.1 339.8**RADIO AIDS TO NAVIGATION:** NOTAM FILE SYA.**SHEMYA (H) (H) VORTACW** 109.0 SYA Chan 27 N52°43.10' E174°03.73' 256° 1.9 NM to fld. 67/3E. VORTAC

unmonitored 0300-1100Z† Mon-Sat; all day Sun &amp; hol.

TACAN AZIMUTH unusable:

289°-029°

VOR unusable:

289°-029°

DME unusable:

035°-045°

057°-085° byd 35 NM

289°-029°

**SHEMYA NDB (HW)** 403 SYA N52°43.32' E174°03.62' 250° 2.0 NM to fld. 60/3E. SHUTDOWN.**ILS 110.1** I-SYA Rwy 28. Glideslope unusable for autopilot cpd apchs blw 300'. Unmonitored 0300-1100Z†

Mon-Sat; all day Sun and hol.

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Cold Bay FSS dial 1-800-478-7250. For a toll free call to Kenai FSS dial 1-866-864-1737. Preventive maint schedule, VOR Fri 1800-2000Z†. Wx for all MP is (600/1.5 +1). TACAN Mon

1800-2000Z†. ILS Tue 1800-2000Z†. CTAF advsy 352.05 unavbl 0300-1100Z† Mon-Sat, Sun and hol. Aft sked arr

CTAF advsy 352.05 avbl one hr prior. PMSV METRO remote wx briefings avbl H24—15 OWS

D312-576-9755/C618-256-9755; 2 hr PN. PMSV METRO—Mil tran acft remote briefing avbl from 3 OSS weather Flt

Elmendorf Metro DSN 552-4903. Manned obs supplemented by ASOS 1000-0200Z†, Mon-Sat, no Sun or hol. RDO

nav fac unmnt 0001-1400Z† dly; cons wkend and hol. Airborne acft declaring acft emerg into Eareckson Air

Strn—Eareckson Metro 127.2 or 352.05 durg ops hr; if no answer—Eareckson Radio on CTAF &amp; call

907-392-3505/3606; ensure Anchorage ATC is aware of emerg. As backup Anchorage ATC durg non ops hr shall notify

Eareckson Radio on 907-392-3505/3606 of all acft emerg. Dur non ops hr Eareckson Air Strn rqr 30 min PN when psbl.

Wx/Aflld Ops—D317-392-4005/C907-392-4005.

**EAST ALSEK RIVER** (See YAKUTAT on page 270)**EDWARD G PITKA SR** (See GALENA on page 116)