

CHESANING**HOWARD NIXON MEML** (50G) 1 W UTC-5(-4DT) N43°10.86' W84°07.95'

DETROIT

641 NOTAM FILE LAN

RWY 09-27: 2800X150 (TURF) LIRL(NSTD)**RWY 09:** REIL. Tree.**RWY 27:** REIL. Thld dsplcd 800'. Road.**RWY 18-36:** 2582X150 (TURF) LIRL(NSTD)**RWY 18:** REIL. Thld dsplcd 400'. Tree.**RWY 36:** REIL. Thld dsplcd 796'. Tree.**SERVICE:** LGT Actvt NSTD REIL Rwy 09. 27, 18 and 36; NSTD LIRL Rwy 09-27 and 18-36—5 clicks CTAF. Rwy 09-27 and Rwy 18-36 NSTD LIRL due to color.**AIRPORT REMARKS:** Attended irreg. Deer and lrg birds and deer on and invof arpt. No winter snow removal. Rwy 18-36 and Rwy 09-27 and dthr mkd with 3' yellow cones.**AIRPORT MANAGER:** 517-974-8039**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490.**CHIPPEWA CO INTL** (See SAULT STE MARIE on page 240)**CLARE****CLARE MUNI** (48D) 1 NE UTC-5(-4DT) N43°50.07' W84°44.41'

DETROIT

856 B NOTAM FILE LAN

L-281, 31C

RWY 04-22: H3500X75 (ASPH) MIRL 0.8% up NE**RWY 04:** REIL. PAPI(P4L)—GA 4.0° TCH 35'.**RWY 22:** REIL. PAPI(P2L)—GA 3.0° TCH 25'.**RWY 09-27:** H2499X75 (ASPH) S-20 MIRL 0.3% up W**SERVICE:** S4 FUEL 100LL LGT ACTIVATE REIL Rwy 04 and Rwy 22; PAPI Rwy 04 and Rwy 22; MIRL Rwy 04-22 and Rwy 09-27—CTAF.**AIRPORT REMARKS:** Attended irregularly. Deer and lrg birds on and invof arpt. 100LL: fuel avbl H24 self svc via credit card. Admin bldg acce: press V, then III & II simul, then I. Rwy ends 04 and 22 faded. Rwy ends 09 and 27 faded.**AIRPORT MANAGER:** 989-386-0445**COMMUNICATIONS:** CTAF/UNICOM 122.8


Ⓡ GREAT LAKES APP/DEP CON 126.45 (1030-0500Z†)

Ⓡ CLEVELAND CENTER APP/DEP CON 127.7 when Great Lakes apch ctl clsd.

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MOP.**MOUNT PLEASANT (L) (L) VORV/DME** 110.6 MOP Chan 43
N43°37.37' W84°44.24' 004° 12.7 NM to fld. 752/5W.

DME unusable:

Byd 33 NM blo 4,000'



DETROIT

L-281, 31C

IAP

DENTON FARMS (M11) 5 SW UTC-5(-4DT) N43°45.23' W84°48.66'

DETROIT

849 NOTAM FILE LAN

RWY 12-30: 2600X100 (TURF)**RWY 12:** Trees.**RWY 30:** Trees.**RWY 01-19:** 1800X100 (TURF)**RWY 01:** Road.**AIRPORT REMARKS:** Unattended. Arpt clsd Nov-Apr. Deer and lrg birds on and invof arpt. Rwy 01-19 irreg, defined by mowing.**AIRPORT MANAGER:** 989-205-7039**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490.**CLARE CO** (See HARRISON on page 195)**CLIFFORD LAKE SPB** (See STANTON on page 244)