122 KANSAS

MINNEAPOLIS CITY CO (45K) 2 SW UTC-6(-5DT) N39°05.66′ W97°43.26′

1246 NOTAM FILE ICT RWY 16-34: H3970X20 (ASPH)

RWY 16: Trees.

RWY 34: Trees

AIRPORT REMARKS: Attended Apr-Nov dawn-dusk. Arpt opr daylight hrs only. Deer on and invof arpt.

AIRPORT MANAGER: 785-392-3300

COMMUNICATIONS: CTAF 122.9

R KANSAS CITY CENTER APP/DEP CON 134.9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at

913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE SLN.

SALINA (VH) (H) VORTACW 117.1 SLN Chan 118 N38°55.51'

W97º37 28' 328° 11.2 NM to fld. 1316/7E.


VOR unusable:

017°-026° bvd 40 NM

315°-016° byd 15 NM blo 6,000′

DME unusable:

300°-042° byd 15 NM blo 6,000°



## MOLINE

ELK CO (2K6) 3 NE UTC-6(-5DT) N37°22.86′ W96°16.27′

KANSAS CITY

WICHITA

L-101

1063 NOTAM FILE ICT

RWY 18-36: H2510X40 (ASPH) 0.4% up N RWY 36: Pole.

AIRPORT REMARKS: Unattended. Wildlife on and invof arpt. Rwy 18-36 has centerline marking only. Rwy 36 the poles that constitute the controlling obstruction on the right are not visibly marked or lgtd.

AIRPORT MANAGER: 620-374-3597 COMMUNICATIONS: CTAF 122 9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

MONTEZUMA MUNI (K17) 2 SW UTC-6(-5DT) N37°35.14′ W100°28.21′ WICHITA

L-15C

2780 NOTAM FILE ICT

RWY 17-35: H4000X60 (ASPH) MIRL

RWY 17: Thid dsplcd 700'. P-line.

RWY 35: P-line.

LGT ACTIVATE MIRL Rwy 17-35-CTAF. SFRVICE-

AIRPORT REMARKS: Unattended. +6' irrigation engine/pump located on Rwy 17-35 W edge near windsock. (Two) +4' natural gas risers located on Rwy 17-35 west edge. Rwy 17 dsplcd thld marked with concrete slabs. Rwy 17-35 p-lines marked with red halls

AIRPORT MANAGER: 620-846-0001 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

MORITZ MEML (See BELOIT on page 88)