NORTH DAKOTA

ROBERTSON FLD (D55) 1 WSW UTC-6(-5DT) N48°45.19' WS 1608 B NOTAM FILE GFK RWY 14-32: H3600X60 (ASPH) S-12.5 MIRL RWY 14-32: H3600X60 (ASPH) S-12.5 MIRL RWY 14: PAPI(P2L)—GA 3.0° TCH 28'. RWY 32: PAPI(P2L)—GA 3.0° TCH 27'. RWY 08-26: 1930X100 (TURF) RWY 26: Road.	98°23.63′ TWIN CITIES L-14g IAP
 SERVICE: FUEL 100LL LGT Actvt PAPI rwy 14 and rwy 32; MIRL rwy NOISE: Noise sensitive area NW quadrant of field, avoid overflight. AIRPORT REMARKS: Attended on call. Large birds and deer on and invof arp 701–370–9710. Self svc fuel avbl 24 hr with credit card. Rwy 08–26 i winter conds/snow removal with arpt manager at 701–370–9710. Ap condition. Cold temperature airport. Altitude correction required at or 1 AIRPORT MANAGER. (701) 370-9710 WEATHER DATA SOURCES: AWOS-3 118.225 (701) 256–2121. COMMUNICATIONS: CTAF/UNICOM 122.8 RMINNEAPOLIS CENTER APP/DEP CON 132.15 CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-55 RADIO AIDS TO NAVIGATION: NOTAM FILE DVL. DEVILS LAKE (DH) DME 114.75 DVL Chan 94(Y) N48°06.91' W9 	t For svcs after hrs ctc arpt manager CLSD winters due to lack of snow removal. Confirm r–Nov. Midfield N/S twy is clsd indef due to poor below –35C.
LARIMORE MUNI (2L1) 1 W UTC-6(-5DT) N47°54.40' W97°3 1130 NOTAM FILE GFK RWY 12-30: H2914X50 (ASPH) S-4 LIRL RWY 12: Rgt tfc. RWY 30: Thid dspicd 87'. Road. SERVICE: LGT SS-SR. AIRPORT REMARKS: Attended Mon-Sat on call. Snow removal irregular Oct t 701-343-2065 or cell 218-779-4244. AIRPORT MANAGER: 218-779-4244 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-55	hru May. For conditions report ctc arpt manager at
LEEDS MUNI (D31) 2 E UTC-6(-5DT) N48°17.10′ W99°24.13 1508 NOTAM FILE GFK	3 ' TWIN CITIES L-14G