
PLATTE MUNI (1D3) 1 NE UTC-6(-5DT) N43°24.28' W98°49.83'

OMAHA
L-12H

1618 B NOTAM FILE HON

RWY 14-32: H3100X60 (CONC) S-125 MIRL 0.5% up SE

RWY 14: PAPI(P2L). Tree.

RWY 32: PAPI(P2L). Trees. Rgt tfc.

SERVICE: FUEL 100LL LGT ACTIVATE MIRL Rwy 14-32—CTAF.

AIRPORT REMARKS: Attended Mon-Sat 1400-2300Z±. Fuel avbl 24 hrs with credit card. During winter months rwy could be slippery, confirm winter conditions with arpt manager call 605-337-2334/3923. Deer and other wildlife on and invof arpt.

AIRPORT MANAGER: 605-337-2334

COMMUNICATIONS: CTAF/AUNICOM 122.8

GCO 121.725 (4 clicks to MINNEAPOLIS CENTER and 6 clicks to FLIGHT SERVICES)

CLEARANCE DELIVERY PHONE: For CD if una via GCO ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE MHE.

MITCHELL (L) (L) VORW/DME 114.15 MHE Chan 88(Y) N43°46.62' W98°02.25' 233° 41.2 NM to fld. 1298/4E.

PRESHO MUNI (5P5) 1 E UTC-6(-5DT) N43°54.36' W100°02.20'

OMAHA

1760 B NOTAM FILE HON

RWY 10-28: 3350X150 (TURF-GRVL) LIRL 0.4% up W

RWY 10: Road.

RWY 28: Fence.

SERVICE: LGT ACTIVATE LIRL Rwy 10-28—CTAF.

AIRPORT REMARKS: Unattended. Wildlife and waterfowl on and invof arpt. Rwy 10-28 center 52' gravel plus gravel turnarounds. Rwy 10-28 marked with black and white cones.

AIRPORT MANAGER: 605-280-4641

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.