

**LONG ISLAND MAC ARTHUR** (See NEW YORK on page 224)

## LONG LAKE

**LONG LAKE/HELMS SPB** (NY9) 0 N UTC-5(-4DT) N43°58.50' W74°25.23'

NEW YORK

1629 NOTAM FILE BUF

**WATERWAY NE-SW:** 15000X1500 (WATER)

**SERVICE:** S2 FUEL 100LL

**SEAPLANE REMARKS:** Attended Jun-Aug 1300Z±-dusk. Bridge acrs lake (Rt 30) 500' W of base. Do not taxi under bridge at high water levels, possible at low water level, stay to west (high) side of bridge. Water levels may vary +/- 10'. P-line at base and building across from base, +50' plines along road and bridge (Route 30). One rwy north of bridge and the other rwy south of bridge.

**AIRPORT MANAGER:** 518-624-3931

**COMMUNICATIONS:** CTAF/UNICOM 122.8

**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.

**LONG LAKE SAGAMORE SPB & MARINA SPB** (KØ3) 1 N UTC-5(-4DT) N43°58.14' W74°25.73'

NEW YORK

1629 NOTAM FILE BUF

**WATERWAY ALL-WAY:** 15000X2000 (WATER)

**SEAPLANE REMARKS:** Attended April-Nov dawn-dusk. Major rwy orientation is NE-SW. Do not taxi under bridge at high water levels, possible at low water levels. Stay to west (high) side of bridge. Water levels vary +/- 10'. Access to Sagamore Base from land side via Owlhead Lane off of Rt 30 north of US Post Office on east side. One rwy north of bridge, another rwy south of bridge. Bridge across lake (Route 30) and building across road. +50' P-lines along road and bridge (Route 30). Sagamore Base located 1/4 mile south of bridge on east shore. SPB located 60 NM east of Carthage, NY.

**AIRPORT MANAGER:** 518-624-5520

**COMMUNICATIONS:** CTAF/UNICOM 122.8

**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.

**LT WARREN EATON** (See NORWICH on page 228)

**LUFKER** (See EAST MORICHES on page 195)

**MALONE-DUFORT** (MAL)(KMAL) 2 W UTC-5(-4DT) N44°51.22' W74°19.74'

MONTREAL

790 B NOTAM FILE BTV

**RWY 05-23:** H3994X100 (ASPH) S-20 MIRL 0.4% up SW

**RWY 05:** REIL. PAPI(P2L)—GA 3.15° TCH 42'. Trees.

**RWY 23:** REIL. PAPI(P2L)—GA 3.0° TCH 43'. Trees.

**RWY 14-32:** H3250X75 (ASPH) S-12.5 MIRL 0.9% up SE

**RWY 14:** Trees.

**RWY 32:** Thld dsplcd 348'. Tree.

**RUNWAY DECLARED DISTANCE INFORMATION**

**RWY 05:** TORA-3994 TODA-3994 ASDA-3994 LDA-3994

**RWY 14:** TORA-3250 TODA-3250 ASDA-3250 LDA-3250

**RWY 23:** TORA-3994 TODA-3994 ASDA-3994 LDA-3994

**RWY 32:** TORA-3250 TODA-3250 ASDA-3250 LDA-2902

**SERVICE:** FUEL 100LL LGT ACTIVATE PAPI Rwy 05 and Rwy 23, MIRL

Rwy 05-23, Rwy 14-32 and twy lgts—CTAF.

**AIRPORT REMARKS:** Airport not attended. Rwy 14-32 has snow removal but visual inspection and NOTAM check must be done as town roads are plowed before arpt. Haying activity and equipment present Jun-Sept.

**AIRPORT MANAGER:** (518) 483-4740

**WEATHER DATA SOURCES:** AWOS-AV 122.8 (518) 651-2601.


**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ BOSTON CENTER APP/DEP CON 135.25

**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE MSS.

**MASSENA (H) TACAN** Chan 88 MSS (114.1) N44°54.87' W74°43.36' 116° 17.2 NM to fld. 198/14W.



**MARCY FLD** (See KEENE on page 210)